

NMOC

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth, interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries);				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TOP TRUE VERT. DEPTH
			Squeezes: Set 5 1/2" cmt retainer @ 7530' Pump 8 bbl Class "G" neat cmt below cmt retainer @ 7580' Pump 12.5 bbl Class "G" neat cmt @ 7055-7580' Pump 3.6 bbl Class "G" neat cmt @ 6129-6283' Set CIBP @ 5950'	Ojo Alamo Kirtland Fruitland PC Lewis Cliffhouse Monefee Gallup Dakota	1347 1377 2622 3047 3194 4932 4997 6552 7644	