Casing S Csg.Perf.	@ 	_w <u>`</u>	Sx.	ı. ft. Int		w_	Spd. Cu. ft. Sx. Pr. Prod. Stim	@ ·		t w	Cu. ft. Sx. T.		°B	† Gas
Ρ	BO/D MCF/D A	ter	Hrs.	SICP_	Р	SI After	Grav		1st De	el. Gas				A N S
TOPS		Hrs. SICP PSI After Days GOR NITD X Well Log				TEST DATA						 -		
Ojo Alamo			C-103			Plat	X	Schd.	PC	0	T		т	
Kirtland			C-104			Electric Lo		Jenu.			PW	PD	D	Ref. No
Fruitland						C-122		-		 	 	ļ	<u> </u>	——
Pictured Cliffs		-	Ditr			Dfa		 		ļ	 		L	↓
Chacra			Datr			Doc		 			 			
Cliff House						1000					ļ			
Menefee														
Point Lookout														
Mancos								ļ						
Gallup								 						
Greenhorn	+													
Dakota														
Entrada														
							N/328.94 Acres							
Blanco M								L						L

Atlantic A #8R H-29-31N-10W

MERIDIAN OIL INC.



United States Department of the Interior

TAKE
PRIDE IN
AMERICA

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401

IN REPLA REFER TO. SF-078389 et al. (WC) 3162.3-1.0 (019)

DEC. 4 1001



Meridian Oil Inc. PO Box 4289 Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill the following wells:

- V^{1} . No. 101 Lucerne A Com, Sec. 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- 2. No. 265 Rosa Unit, Sec. 27, T. 31 N., R. 5 W., Rio Arriba County, New Mexico, lease SF-078770.
- No. 500 Summit Viles, Sec. 33, T. 29 N., R. 11 W., San Juan County, New Mexico, lease SF-047019-A.
- 4. No. 213 San Juan 32-9 Unit, Sec 14, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-01594.
- 45. No. 102 Lucerne A, Sec 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- 6. No. 100 Lucerne A, Sec 3, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- 7. No. 500 Angel Peak B, Sec 13, T. 28 N., R. 11 W., San Juan County, New Mexico, lease SF-047017-A.
- B. No. 101 East, Sec 25, T. 31 N., R. 12 W., San Juan County, New Mexico, lease SF-077652.
- 9. No. 8R Atlantic A, Sec 29, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-0606.

As discussed with Peggy Bradfield of your company on, November 20, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that

ABANDONED LOCATION

construction activities have in fact occurred, may result in assessment of liquidated damages.

sincerely, |s| John L. Koller

John L. Keller Chief, Branch of Mineral Resources

9 Enclosures

CC: New Mexico Oil Conservation Division, Aztec, NM