## UNITED STATES

## DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT REALM

	ices and Reports on We	Tas Ku	
Type of Well GAS	070 FA	6.	Lease Number SF-078507 If Indian, All. o Tribe Name
Name of Operator	La companya de la casa	7.	Unit Agreement Na San Juan 32-9 Uni
<del>-</del>	& GAS COMPANY DEC	EIVEN	
Address & Phone No. of Opera PO Box 4289, Farmington, NM	tor   11 DE 87499 (505) 326-9700	COM. DIV.	Well Name & Numbe San Juan 32-9 U#2 API Well No. 30-045-27901 Field and Pool
Location of Well, Footage, Some 790'FSL 955'FWL, Sec.25, T-3	, -,	Diality 2	Basin Fruitland C County and State San Juan Co, NM
. CHECK APPROPRIATE BOX TO IN			DATA
Type of Submission _X_ Notice of Intent	Type of A	Change of Pla	
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construct Non-Routine Water Shut of	Fracturing
Final Abandonment		Conversion to	o Injection
. Describe Proposed or Comp	leted Operations		
It is intended to recavit	ate the subject well i	n the following :	manner:
MIRU. Pull the tubing. Pu formation utilizing natur Clean the well to TD and be pre-perforated 4 SPF a tubing. The well will the	ral and air assisted surun a 5 ½", 15.5#, K-5 cross the coal interva	rges until the works of casing liner. 'als. Re-run the part of the	ell stabilizes. The liner will
. I hereby certify that the	foregoing is true and	correct.	
mad Japan Shall be	Title Regulatory A	dministrator_Dat	e 11/25/98
gued stiffed statements.	,		TLW