Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: September 30, 1990

CAPITOS.	- Sep	CHIOCI	50,	 "
				_

SUNDRY NOTICES A	SF - 078513						
Do not use this form for proposals to drill Use "APPLICATION FOR	Marie Carlos Car						
SUBMIT I. 1. Type of Well	17. If Unit or CA, Agreement Designation						
OIL GAS WELL OTH	ER NEGETY:	8.ºWell Name and No. Arnaud A 1					
2. Name of Operator Amoco Production Company	9. API Well No.						
3. Address and Telephone No.	30-045-28182						
P.O. Box 3092 Houston, tx 77352	10. Field and Pool, or Exploratory Area						
4. Location of Well (Footage, Sec., T., R., M., or Survey	(281) 366- 4491	Basin Fruitland Coal 11. County or Parish, State					
1850' FNL & 1090' FEL Sec. 17 T3	San Juan New Mexico						
12. CHECK APPROPRIATE BOX(s							
TYPE OF SUBMISSION	N ON OTHER BATA						
☐ Notice of Intent	Abandonment	Change of Plans					
Subsequent Report		New Construction					
Final Abandonment Notice	☐ Plugging Back☐ Casing Repair	Non-Routine Fracturing Water Shut-Off					
	☐ Altering Casing ☑ Other WELL REPAIR	Conversion to Injection					
	ompletion on Well Completion or n.)						
13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 10/12/1999 MIRUSU Pressure test BOP. Blow down well. TOH w/TBG. TIH & C/O well w/air. Tag bottom @ 3727'. Drill 8' new hole to 3735. NOTE: PERMISSION PER PHONE CONVERSATION MIKE KUTAS (AMOCO) &							
WAYNE TOWNSEND (BLM) ON 10/17/1999. COTB to 3735'. Flow well. TIH to 3721' tag fill. RU reamer. TIH to 3420'. Break circ & underream from 3420' to 3622'. @ 3622' coal flowing into well. Pressure from 700 - 1200 PSI. TOH w/reamer. TIH w/new bit & tag fill @ 3491'. COTB from 3491' - 3543'. Formation flowing coal. Shut down rig & all other EQPT on location. Safety Stand down.							
Blow down well (805 PSI). TIH to 3505 tag fill. COTB from 3505' - 3512'. Continue COTB to 3543' - 3606. TOH. TIH w/underreamer. Break circ. Underream from 3425' - 3735' TD. Circ hole. TOH w/reamer. RU to cavitate. TIH to 3470' tag fill. PU Break circ. COTB from 3470' - 3735'. Flow well. TIH to 3521' tag bridge. Brak Circ. Drill on bridge. Dry up hole & TOH. TIH w/new bit tag bridge @ 3515' COTB 3515' - 3536' Hard drilling. COTB 3536' - 3566' heavy coal returns. COTB 3568' - 3600'. Coal flowing heavy. COTB 3548' - 3568' Heavy coal. COTB 3568' - 3663'. COTB 3693' - 3735'. Flow well for fill check. Flow well on 3/4" choke - end PSI 40# 590 MCFD. Well loaded w/WTR. Flow well for clean up. COTB 3615' - 3735'. Dry up well. TOH. TIH w/ 5 1/2" liner & hanger &							
set @ 3735'. TOH. RU & perf 3463' - 3468'; 3483' - 3518' ; 3635' - 3640'; 3621' - 3726'. Test w/well pressure. Blow down well. TIH w 2 3/8" TBG & land @ 3719'. ND BOP. NU tree & test 15 min. 1500# PSI good.							
10/30/199 RDMOSU							
14. I hereby certify that the foregoing is true and correct							
Signed Mary Corley	Title Sr. Business Analyst	Date12/01/99					
(This space for Federal of State office used							
Approved by Conditions of approval, if any:	Title	Date					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any force, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.