

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <hr/> <p>2. Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY</p> <hr/> <p>3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <hr/> <p>4. Location of Well, Footage, Sec., T, R, M 1445' FSL, 1295' FWL, Sec. 36, T-32-N, R-8-W, NMPM, San Juan County</p>	<p>API # (assigned by OCD) 30-045-28566</p> <p>5. Lease Number</p> <p>6. State Oil&Gas Lease # K-5808-NM</p> <p>7. Lease Name/Unit Name Albino Canyon</p> <p>8. Well No. #101</p> <p>9. Pool Name or Wildcat Basin Fruitland Coal</p> <p>10. Elevation:</p>
---	---

Type of Submission	Type of Action
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input checked="" type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other - Sidetrack
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

The subject well is an under performing cased, cemented, perforated and fracture stimulated coal well surrounded by open hole un-cemented liner completions. It is intended to plug and abandon the existing 4-1/2" cemented liner over the coal, set a whipstock in the 7" topset at the 4-1/2" liner top, and "blind" sidetrack a new 6-1/4" open hole interval through the coal in the same wellbore to maintain qualified tax credits. A pre-perforated un-cemented 5-1/2" liner will then be run following underreaming and cavitation. CIBP's will be set according to the following:

A CIBP will be set @ 3560' in the existing 4-1/2" cemented liner. Spot minimum 50' cement plug on top of CIBP. Cement with 10 sacks of Class H neat cement with 2% calcium chloride (1.18 cu. Ft./sx). TOOH. Circ hole clean. Set CIBP @ 3440' in the existing 4-1/2" cemented liner approximately 50' below the liner top. Spot minimum 50' cement plug on top of CIBP. Cement with 10 sacks of Class H neat cmt with 2% calcium chloride (1.18 cu. Ft./sx). TOOH. Circ hole clean. Proceed with drill out of cement to 4-1/2" x 7" liner top, whipstock out of 7", sidetrack and cavitation operations.

See attached wellbore diagram.

SIGNATURE  Regulatory Supervisor September 6, 2001

TLW

(This space for State Use)

Approved Original Signed by STEVEN N. HAYDEN

Title

Date

DEPUTY OIL & GAS INSPECTOR, DIST. #3

SEP 10 2001

Albino Canyon #101 (proposed)

Fruitland Coal
Unit K, Section 36, T32N R8W, San Juan County, NM

