Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 200

	01,110,100		
	Expires: November 30	0, 20	)(
Leas	e Serial No.		

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals APR 2001

Convert to Injection

SF-078389A

Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICA	ATE - Other instruction		N. D#V	7. TrUnit or CA/Agreer	ment Name and/or No.	
1. Type of Well Oil Well O	Gas Well Other	COAL BENTMETHANE	F. 3	Well Name and No.		
Name of Operator     BURLINGTON RESOURCES OIL	& GAS	E LIN	E OE 66.00	9. API Well No. 3004528887	UNII 223	
3a. Address 3401 EAST 30TH FARMINGTON, NM		3b. Phone No.(include are 505.326.9727	a code)	10. Field and Pool, or Exploratory Area BASIN FRUITLAND COAL		
4. Location of Well (Footage, S	,	11. County or Parish, and State SAN JUAN NM				
12. CHECK APPRO	PRIATE BOX(ES) TO INDI	CATE NATURE OF NOT	ΓΙCE, REP	ORT, OR OTHER DA	TA	
TYPE OF SUBMISSION		TYPE OF	ACTION			
☐ Notice of Intent  Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	Deepen Fracture Treat New Construction	Reco	Production (Start/Resume) Wat Reclamation Wel Recomplete Oth		
Final Ahandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temp	orarily Abandon		

☐ Plug Back

☐ Water Disposal

10

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be files within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

(2-22-01) MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. SDON.(2-23/3-30-01) TIH w/bit. Blow well & CO to TD @ 3146'.(3-31-01) TOOH w/bit. TIH w/6 jts 5-1/2" 15.5# K-55 LT&C csg, set @ 3146'. Lnr top @ 2927'. Lnr pre-perf @ 2975-3059', & 3123-44' across coal interval. TIH w/perf mill. Mill perf plugs @ 2975-3059', & 3123-44'. TOOH w/perf mill. SDON.(4-1-01) TIH w/98 jts 2-3/8" 4.7# J-55 tbg, set @ 3115'. SN @ 3082'. ND BOP. NU WH. RD. Rig released.

Electronic Submission #3398 verified by the BLM Well Information System for	BURLING	GTON RESOURCES OIL & C	AS Sent to the l	Farmington Field Office
Committed to AFMSS for processing by Maurice Johnson on 04/10/2001  Name (Printed/Typed) PEGGY COLE	Title		UTHORIZER	
Signature	Date	04/04/2001		
THIS SPACE FOR FEDER	AL OR	STATE OFFICE USE	*CEDTE	FOR RECOR
Assessed Day		Title	ړنږ	Hate on 1
Approved By  Conditions of approval, if any, are attached. Approval of this notice does not war certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	lease	Office	<u> </u>	_ urrice