State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	API	# (assigned by OCD)
		30-045-28957
Type of Well	5.	Lease Number
GAS	_	Fee
	6.	State Oil&Gas Lease
Name of Operator	7.	Lease Name/Unit Name
BURLINGTON		
RESOURCES OIL & GAS COMPANY		Allison Unit
	8.	Well No.
Address & Phone No. of Operator		1R
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Pool Name or Wildcat Basin Dakota
Location of Well, Footage, Sec., T, R, M	10.	Elevation:
1915'FNL, 655'FWL, Sec. 17, T-32-N, R-6-W, NMPM, San Juan		
Type of Submission Type of Action		
	ange of Pla	
 -	w Construct	
	n-Routine ter Shut o:	
		o Injection
X Other -	nverbren e.	2,00010
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser attached procedure and wellbore diagram.	ıck. It is	intended to free the
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser	nck. It is	DEC 3 1 1996
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser	nck. It is	DEC 3 1 1996
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser attached procedure and wellbore diagram.	ock. It is to pump acc	DEC 3 1 1996 COMO DIVI.
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser attached procedure and wellbore diagram. IGNATURE Jayun Shaahuul (KM6) Regulatory Admin.	ock. It is to pump acc	DEC 3 1 1996 COMO DIVI.
On December 15, 1996 Burlington Resources rigged up or an insert pump. The tubing was found to be stu stuck tubing and continue to install the inser attached procedure and wellbore diagram.	ock. It is to pump acc	intended to free the cording to the DEC 3 1 1996 CONODINA DISTO 3

FREE STUCK TUBING PROCEDURE

ALLISON UNIT #1R
DPNO: 36914A
Fruitland Coal
Sec. 17, T32N, R06W, SJC, NM

Project Summary: On December 15, 1996, we rigged up on the Allison Unit #1R to install an insert pump. When we attempted to pull the tubing we were only able to pull up 19" with a 68,000 lb. pull. This calculates out to a free point of 911' from surface. This is a three year old wellbore with reasonably good cement coverage. The purpose of this project is to determine the cause of the stuck tubing, repair it, and continue with the pump installation. Note: BHP = 1675 psi.

- 1. Comply with all NMOCD, BLM and BROCG rules and regulations.
- MIRU 24 hour workover rig with air package. Kill well with produced water. ND wellhead and NU BOP. MIRU wireline company. Run free point on tubing. Run string shot and back off tubing above free point. POOH.
- Deliver 2-7/8" / 2-3/8" N-80 workstring. RIH with 4 to 6 drill collars, bumper sub, accelerator, and jars on workstring. Screw on to fish and attempt to jar tubing loose. If this fails then back off of fish and POOH. Coordinate additional fishing with Drilling Superintendent and Operations Engineer.
- 4. If jarring freed the tubing, then POOH with tubing string. RIH with tapered mill for 7" casing to liner top at 3610', POOH. RIH with tapered mill for 4-1/2" casing to PBTD. POOH.
- 5. RIH with RBP and set in 4-1/2" casing at approximately 7800'. Spot sand on top of RBP. Load hole and test casing to 1000 psi. If casing test fails then coordinate squeeze procedure with Drilling Superintendent and Operations Engineer. If casing tests then circulate sand off of RBP, release RBP and POOH laving down workstring.
- 6. Continue with pump installation procedure.

		Approve:	Operations	2/27/ Engineer	19	
			Drilling Su	perintendent		
		Concur:	Production Superintendent			
Contacts:	Operations Engineer	Kevir	n Midkiff	326-9807 (Office) 564-1653 (Pager)		
	Production Foreman	Cliff	Brock	326-9818 (Office) 326-8872 (Pager)		


Allison Unit #1R (

Current -- 9/17/96
DPNO: 36914A
Basin Dakota

1915' FNL, 655' FWL Unit E, Sec. 17, T32N, R06W, San Juan County

Spud: Completed : Elevation: 7/6/93 9/21/93 6548' GL

Logs:



TD @ 8090'

ote: When well is soaped, w	eii makes 50 bw	d and 900 Mc	1/d						
Cumulative as of 1996 Current as of 9/96	:	529 MMcf 344 Mcf	0 bo 0 bo	50 bwd	Gross EUR Gross Remaining Res	serves	6255 5726	MMcf MMcf	
PRODUCTION HISTORY:		Gas	Oil	<u>Water</u>	RESERVE INFORMAT	TON:	Gas		
WORKOVER HISTORY:	None				* ***				
STIMULATION:	70Q N2 Foam:	47 Mgal, 40#	gel, 3.7 MMcfn2	, 120M lbs 20/4) sd				
PERFORATIONS	7 937'- 7943', 79	80'-8022' - 4 (SPF				-	·	
LOGGING:	CNG-LDT/DIL.	GR, CAL. CS	NG. TS	······································					
FORMATION TOPS:	Ojo Alamo Kirtland Fruitland Coal Pictured Cliffs Mesaverde Menefee		2308' 2405' 2945' 3368' 5515' 5506'		Point Lookout Mancos Gallup Greenhorn Graneros Dakota	5662° 6185° 6765° 7760° 7815° 7935°			
Tubing	2-3/8" 4.7# J55, EUE, 8Rd 8027' Tubing F Nipple 1 jt. off btm. @ 7994'								
6-1/4"	4-1/2"	11.6#	_	3610' - 8059' collar set @ 804		4	81 sxs		4650' (C
8-3/4"	7	23#	N80. LT&C	3800	Casing		98 sxs		200° (T
12-1/4"	9-5/8"	36#	K55, 8Rd.	219'	Casing		30 sxs		Surf
CASING RECORD: HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CF	PBTD: MENT	8042'	тос
OWNERSHIP:	GWI: NRI: SJBT:	54.0568% 46.0333% 0.1454%			DRILLING:	CO	UD DATE: MPLETED: LL DEPTH:	7/6/93 8090'	•
	Unit E, Sec. 17, San Juan Count				INITIAL SITP: LAST AVAILABLE SIT	P :	2380	Psig Psig	
LOCATION:	1915' FNL, 655'				INITIAL POTENTIAL:	7	2 MMcfd	AOF	
WELL TYPE:	Basin Dakota						548' 560'		
WELLNAME:	Allison Unit #10				DP NUMBER: PROP. NUMBER:		914A 97971400		