## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

API # (assigned by OCD) 30-045-29615 5. Lease Number Fee GAS  2. Name of Operator  **EFF 2 2 1.37**  **Other holds		Su	ndry Notices and Re	eports on Wells	
1. Type of Well  GAS  2. Name of Operator  BUSINEESN  OIL & GAS COMPANY  3. Address & Phone No. of Operator  PO BOX 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Pootage, Sec., T, R, M 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMFM, San Juan County  Type of Submission  Type of Action  Notice of Intent  Abandoment  Recompletion  Non-Routine Fracturing  Casing Repair  Altering Casing Conversion to Injection  ACTION Company MIRU, ND WH, NU BOP. TOOH w/2-3/8" tbg, TIH w/mill. SDON.  9-8-99  MIRU, ND WH, SDON.  9-9-99  MIRU, ND WH, SDON.  9-10-99  TIH w/one 2" x l %" x 20' RNAC-Z pump & rods. PT & pump action,  OK, RD, Rig released.  SEP 22 1936  TIN  CThis space for State Use)  DEFUIT OIL & GAS INSPETIOR DIST. SEE TAN  SEP 22 1936				API	
2. Name of Operator  RESOURCES  OIL & GAS COMPANY  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMFM, San Juan County  Type of Submission Notice of Intent Abandonment New Construction Now Construction Non-Routine Fracturing Casing Repair Water Shut off Subsequent Report Pinal Abandonment Altering Casing Conversion to Injection X. Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH W/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TH W/256 jts 2-3/8" 4.78 J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TH W/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SEP 22 1996  (This space for State Use)  ORIGHNAL SIGNED BY CHARRLET, PERSEN  DETUTY OIL & GAS INSPECTOR. DIST. #\$  SEP 22 1996	1. Type of We	ell		5.	
2. Name of Operator  RESOURCES  OIL & GAS COMPANY  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMFM, San Juan County  Type of Submission Notice of Intent Recompletion Notice of Intent Casing Repair Altering Casing Conversion to Injection X. Subsequent Report Pluging Back Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection X. Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Took w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 ½" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SEP 22 1906	GAS			DE HORE	
2. Name of Operator  RESOURCES  OIL & GAS COMPANY  3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well, Footage, Sec., T, R, M 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMFM, San Juan County  Type of Submission Type of Action Notice of Intent Abandonment Recompletion Pinal Abandonment Altering Casing Repair Non-Routine Practuring Altering Casing Conversion to Injection Coher - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOD. TOOH W/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOD. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SEP 22 1996  CTIN Well No. 10. NO. 10. NO. 10. NO. 10. NO. 10. NO. 10. NO. NO. RD. Rig released.  SEP 22 1996  CTIN Well No. 10. NO. NO. RD. Rig released.  SEP 22 1996  CTIN OF A COMPANY OF A CONTROL					State Oil&Gas Lease #
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 9. Pool Name or Wildcat Blanco MV/Basin DK 4. Location of Well, Footage, Sec., T, R, M 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMPM, San Juan County  Type of Submission Type of Action Notice of Intent Abandonment Recompletion New Construction Plugging Back Non-Routine Fracturing Casing Repair Attering Casing Conversion to Injection Cher - pump installation  13. Describe Proposed or Completed Operations  14. Describe Proposed or Completed Operations  15. Describe Proposed or Completed Operations  16. Elevation:  Type of Action New Construction N			SE	P 2 2 1833 3	Lease Name/Unit Name
PO Box 4289, Farmington, NM 87499 (505) 326-9700  9. Pool Name or Wildcat Elanco MV/Basin DK 2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMFM, San Juan County  Type of Submission  Type of Action  Notice of Intent  Abandonment  Recompletion  New Construction  Non-Routine Fracturing  Casing Repair  Water Shut off  Final Abandonment  Altering Casing Conversion to Injection  X Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99  MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON.  9-8-99  Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well.  9-9-99  TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP.  NU WH. SDON.  9-10-99  TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action,  OK. RD. Rig released.  SEP 2.2 1990  (This space for State Use)	RESO	プラナング・ファマン <sup>*</sup> *	COMPANY		
Blanco MV/Basin DK  4. Location of Well, Footage, Sec., T, R, M  2640'FNL, 15'FEL, Sec.18, T-32-N, R-6-W, NMPM, San Juan County  Type of Submission  Type of Submission  Notice of Intent Abandonment Change of Plans Recompletion New Construction  X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Altering Casing Conversion to Injection X Cother - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE  Regulatory Administrator_September 20, 1999  TIN  TIN  TIN  TIN  SEP 2 2 1990	3. Address &	Phone No. of Operator		The second second	#39
Type of Submission  Type of Action  Notice of Intent  Abandonment  Eccompletion  Non-Routine Fracturing  Abandonment  Subsequent Report  Plugging Back  Non-Routine Fracturing  Casing Repair  Altering Casing  Conversion to Injection  Cother - pump installation  13. Describe Proposed or Completed Operations  9-7-99  MIRU. ND WH. NU BOP. TOOH W/2-3/8" tbg. TIH w/mill. SDON. 9-8-99  Tooh w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP.  NU WH. SDON. 9-10-99  TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action,  OK. RD. Rig released.  SEP 22 1990  CThis space for State Use)  ORIGINAL SIGNED BY CHAPLIE T. PERFERN  DETUTY OH. & GAS INSPECTOR, DIST. AS SEP 22 1990	PO Box 42	289, Farmington, NM 874	99 (505) 326-9700	9.	
Type of Submission  Notice of Intent Abandonment Recompletion New Construction New Construc				=	Elevation:
Motice of Intent Recompletion New Construction  X Subsequent Report Plugging Back Non-Routine Fracturing Plugging Back Non-Routine Fracturing Altering Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIW  (This space for State Use)  ORIGINAL SKONED BY CHAPLIET, PERPAN DETUTY OH. & GAS INSPECTOR, DIST. #5  SEP 2.2 1990					
Recompletion New Construction  X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up © 7860'. CO to CIBP © 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set © 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIM  TIM  TIM  SEP 22 1990					ans
X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Tooler Conversion to Injection X Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIM  (This space for State Use)  ORIGINAL SIGNED BY CHARLE T. PERRIN DETUTY OHL & GAS INSPECTOR, DIST. SEP 22 1990	N				
Casing Repair Water Shut off Altering Casing Conversion to Injection  Z Other - pump installation  13. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 ½" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIW  (This space for State Use)  ORIGINAL SIGNED BY CHAPLIET. PERPENN DETUTY OH. & GAS INSPECTOR, DIST. SEP 2 2 1990	X Si				
TIME  Total State Use)  Other - pump installation  2. Other - pump installation  3. Describe Proposed or Completed Operations  9-7-99 MIRU. ND WH. NU BOP. TOOH w/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIM  (This space for State Use)  ORIGINAL SIGNED BY CHAPLIE T. PERSON  DETUTY ONL & GAS INSPECTOR, DIST. AS SEP 2.2 1990					
9-7-99 MIRU. ND WH. NU BOP. TOOH W/2-3/8" tbg. TIH w/mill. SDON. 9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TLW  (This space for State Use)  ORIGINAL SIGNED BY CHARLE T. PERMAN.  PETUTY OIL & GAS INSPECTOR, DIST. #8 SEP 2.2 1990	F				o Injection
9-8-99 Tag up @ 7860'. CO to CIBP @ 7884'. D/O CIBP. CO to PBTD. Blow well. 9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP. NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIW  (This space for State Use)  ORIGINAL SIGNED BY CHAPLE T. PERRAN  PETUTY OH. & GAS INSPECTOR, DIST. SEP 2.2 1990		•			
9-9-99 TOOH w/mill. TIH w/256 jts 2-3/8" 4.7# J-55 tbg, set @ 8009'. ND BOP.  NU WH. SDON. 9-10-99 TIH w/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TLW  (This space for State Use)  ORIGINAL SIGNED BY CHAPLE T. PERRON  SEP 2.2 1990	9-7-99				
9-10-99 TIH W/one 2" x 1 %" x 20' RWAC-Z pump & rods. PT & pump action, OK. RD. Rig released.  SIGNATURE Regulatory Administrator September 20, 1999  TIM  (This space for State Use)  ORIGINAL SKENED BY CHARLIET. PERSON  SEP 2.2 1990	-	TOOH w/mill. TIH w/25			
SIGNATURE Regulatory Administrator_September 20, 1999  (This space for State Use)  ORIGINAL SIGNED BY CHARLIE T. PERSON  DEPUTY ON & GAS INSPECTOR, DIST. SEP 2.2 1990	9-10-9		20' RWAC-Z pump &	rods. PT & pum	p action,
(This space for State Use)  ORIGINAL SIGNED BY CHARLIE T. PERDAN SETUTY OIL & GAS INSPECTOR, DIST. #8 SEP 2 2 1990		OK. RD. Rig releas	sed.		
(This space for State Use)  ORIGINAL SIGNED BY CHARLIE T. PERDAN SEPUTY OIL & GAS INSPECTOR, DIST. #8 SEP 2 2 1990					
(This space for State Use)  ORIGINAL SIGNED BY CHARLIE T. PERRAN  SETUTY OIL & GAS INSPECTOR, DIST. #8 SEP 2.2 1990	SIGNATURE	Sugar Cale	Regulatory Admi	nistratorSept	ember 20, 1999
ORIGINAL SIGNED BY CHARLIE T. PERRIN DEPUTY OIL & GAS INSPECTOR, DIST. 48 SEP 22 1990					TLW
Approved by Title Date Date	_				<b></b>
			ener du sellas	GAS INSPECTOR, DIST.	Date SEP 22 1999