Submit 3 Copies

State of New Mexico

to Appropriate District Office	Energy, Minerals and						
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERV 2040 I	ATIC Pacheco		ON WELL A		72	
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210	Santa Fe	, NM	87505	5. Indica	30-045-303 ate Type of Lease		П
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				6. State	S1A Oil & Gas Lease N	TE X	FEE
SUNDRY NO	TICES AND REPORTS	ON WE	ELLS				
	ROPOSALS TO DRILL OR TO ERVOIR. USE "APPLICATION C-101) FOR SUCH PROPOSAL	FOR P	A STANKE STANKE	~^^\	Name or Unit Age	reement N	Vame
I. Type of Well: OIL GAS WELL WELL WELL	OTHER	11.57	DEC 2000	SET SET			
2. Name of Operator		£.53	OIL CON. DIV	8 Well	No.		
ross Timbers Operating Com	pany	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	CIST. 3	<i> </i> #2			
 Address of Operator 700 Farmington Ave., Bldg. 	K. Ste 1 Farmington.	NM 87	461		name or Wildcat Dakota / Blar	nco Mes	averde
4. Well Location			C. 299.35	7			
Unit Letter 0 : 667	Feet From The S	outh	Line and	1762'	Feet From The	East	Line
Section 16	Township 31N	Raı	nge 12W	NMPM	San Ju	ian	County
	10. Elevation (Sho	w wheth	er DF, RKB, RT, GR 91' Ground Leve	, etc.)			
11. Check A	ppropriate Box to Ir				nort or Oth	or Dat	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
III LIIELK A	ppropriate bux to in	luicau	E TAULUTE OF TA	once, ice	port, or Our	ei Dai	a
NOTICE OF IN	TENTION TO:		1	UBSEQU	ENT REPO	RT OF	:
NOTICE OF IN	TENTION TO: PLUG AND ABANDON		1	UBSEQU		RT OF	_
NOTICE OF IN			S		ALTERIN	IG CASIN	_
NOTICE OF IN	PLUG AND ABANDON		SI REMEDIAL WORK	LING OPNS.	ALTERIN PLUG AF	IG CASIN	ıg [
NOTICE OF IN	PLUG AND ABANDON		REMEDIAL WORK	LING OPNS. DICEMENT JO	ALTERIN PLUG AF	IG CASIN	ıg [
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER:	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reacher	LING OPNS. DICEMENT JO	ALTERIN PLUG AF	NG CASIN	DONMENT [
NOTICE OF IN ERFORM REMEDIAL WORK EMPORABILY ABANDON ULL OR ALTER CASING THER: 12. Describe Proposed or Completed C	PLUG AND ABANDON CHANGE PLANS OperationsClearly state all per	tinent de	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reached	LING OPNS. D CEMENT JO T T T T T T T T T T T T T T T T T T T	ALTERIN PLUG AN DB	NG CASIN	DONMENT [
NOTICE OF IN PERFORM REMEDIAL WORK EMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Comp	PLUG AND ABANDON CHANGE PLANS Operations Clearly state all per	tinent de	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reached stails, and give pertir	LING OPNS. D CEMENT JO T T T T T T T T T T T T T T T T T T T	ALTERIN PLUG AN DB	NG CASIN	DONMENT [
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Comple	PLUG AND ABANDON CHANGE PLANS Operations Clearly state all per reached a Total Depth the well from TD to the set 4-1/2", 10.5# of lite cement (11.4 per of cement was found	tinent de h of 7, he surf casing ppg, 2. at 400	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reached stails, and give pertir 531' KB on 12/ casing. g at a depth of 58 cuft) and 3 ' KB by temp s	LING OPNS. D CEMENT JO T TD T TD T T T T T T T T T T T T T	ALTERING PLUG AND PLU	y was coppg, 1.5	DONMENT DONMENT DONME
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Comple	PLUG AND ABANDON CHANGE PLANS Operations Clearly state all per reached a Total Depth the well from TD to th ers set 4-1/2", 10.5# of lite cement (11.4 p) p of cement was found the well is shut in and	tinent de h of 7, he surf casing ppg, 2. at 400 awaiti	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reaches stails, and give pertir 531' KB on 12/ casing. g at a depth of 58 cuft) and 3. ' KB by temp s ing completion.	LING OPNS. D CEMENT JO T TD T TD T T T T T T T T T T T T T	ALTERING PLUG AND PLU	y was coppg, 1.5	DONMENT () arting any properties and the content of the content o
NOTICE OF IN ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Complete Compl	PLUG AND ABANDON CHANGE PLANS Operations Clearly state all per reached a Total Depth the well from TD to the set 4-1/2", 10.5# of lite cement (11.4 per per of cement was found to the well is shut in and the set of the s	tinent de h of 7, he surf casing ppg, 2. at 400 awaiti	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reached stails, and give pertir 531' KB on 12/ casing. g at a depth of 58 cuft) and 3. O' KB by temp s ing completion.	LING OPNS. D CEMENT JO D TO THE TO TH	ALTERING PLUG AND PLU	was coppg, 1.3	emented 28 cuft) in
NOTICE OF IN ERFORM REMEDIAL WORK EMPORABILY ABANDON ULL OR ALTER CASING THER: 12. Describe Proposed or Completed Complet	PLUG AND ABANDON CHANGE PLANS Operations Clearly state all per reached a Total Depth the well from TD to th ers set 4-1/2", 10.5# of lite cement (11.4 p) p of cement was found the well is shut in and	tinent de h of 7, he surf casing ppg, 2. at 400 awaiti	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER: Reaches stails, and give pertir 531' KB on 12/ casing. g at a depth of 58 cuft) and 3. ' KB by temp s ing completion.	LING OPNS. D CEMENT JO D TO THE TO TH	ALTERING PLUG AND PLU	y was coppg, 1.3	DONMENT DONMENT DONME

TITLE _

_ DATE _

APPROVED BY_