(SUBMIT IN TRIPLICATE)

*

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency
Havajo Tribal Lands
Allottee
Lease No. 14-20-603-590

SUNDRY NOTICES AND REPORTS ON WELLS

							7
NOTICE OF INTENTION TO DRILL					UT-OFF		
IOTICE OF INTENTION TO CHANGE PLANS	1	SUBSEC	UENT REPORT	OF SHOOTING	OR ACIDIZING_		-
OTICE OF INTENTION TO TEST WATER SH	i i	11	QUENT REPORT				
OTICE OF INTENTION TO REDRILL OR RE					IG OR REPAIR		
OTICE OF INTENTION TO SHOOT OR ACIE		11	QUENT REPORT				
OTICE OF INTENTION TO PULL OR ALTER		11	EMENTARY WELL				
OTICE OF INTENTION TO ABANDON WELL		X					
OTICE OF INTENTION TO ABANDON WELL							
(INDICATE AB	OVE BY CHECK MARK	NATURE OF F	REPORT, NOTICE	, OR OTHER DA	ATA)	•	
		*********		Jenuer	y 10	, 19	53
Bavajo 590 ell No is locate	d 1885 ft. fr	om [N] Jir	ne and 🏂	ft. fron	$\mathbf{n} \left\{ \begin{array}{c} \mathbf{w} \\ \mathbf{w} \end{array} \right\}$ line of	of sec	
Mi/4 Section 36	(Twp.)	(Range)	<u>v</u>	M.M.P.	.M.		
(¼ Sec. and Sec. No.)	(TAD-)	_			ow Mostlet		
(Field)	Count	y or Subdivisio	n)		(State or Territor	Z)	
		AILS OF	and langths of t	proposed casin ork)	gs; indicate mu	dding jobs, cer	ı e n
ive propose to plug and a special depths to object to plug and a special plugs and so in and so our	ing points, and all abundon was 6590-6450, t of interp	izes, weights, other import	WORK and lengths of gent proposed w	-5950, 3	790- 3690	(this pl	
1. Sect escent place	ing points, and all debandon was 6570-6450, t. of interpolarization.	izes, weights, other import	WORK and lengths of gent proposed w	-5950, 3 ring), 1	790-3690 O' to su	(this pi	
We propose to plug an 1. Spot cement plugs 50' in and 50' ou 2. Install dry hole 3. Clean up location Note: Elevation inco-	ing points, and all debandon v 6590-6450, t of integral zerker.	izes, weights, tother import while as 1 6290-61 sediate of	WORK and lengths of grant proposed w college: 190, 6050	.5950, 3 ring), 1 a. 1961	790-3690 O' to sur . ground 1	(this pirace.	
internames of and expected depths to object the propose to plug and 1. Spot cement plugs 50° in and 50° ou 2. Install dry hole 1. Clean up location note: Elevation incompany.	ing points, and all debandon v 6590-6450, t of integral zerker.	izes, weights, tother import while as 1 6290-61 sediate of	WORK and lengths of grant proposed w college: 190, 6050	.5950, 3 ring), 1 a. 1961	790-3690 O' to su	(this pirace.	
internames of and expected depths to object the propose to plug and 1. Spot cement plugs 50° in and 50° ou 2. Install dry hole 1. Clean up location note: Elevation incompany.	ing points, and all debandon v 6590-6450, t of integral zerker.	izes, weights, tother import while as 1 6290-61 sediate of	WORK and lengths of grant proposed w college: 190, 6050	.5950, 3 ring), 1 a. 1961	790-3690 O' to sur . ground 1	(this pirace.	M
ive propose to plug an 1. Spot cement plugs 50' in and 50' ou 2. Install dry hole 3. Clean up location Note: Elevation inco- correct. I understand that this plan of work mand Company Tenneco Oil	d abandon v 6570-6450, t of interpretation asker. company	izes, weights, tother import while as 1 6290-61 sediate of	WORK and lengths of grant proposed w college: 190, 6050	.5950, 3 ring), 1 a. 1961	790-3690 O' to sur . ground 1	(this pirace.	