

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☒ gas well ☐ other

2. NAME OF OPERATOR  
WTR OIL COMPANY

3. ADDRESS OF OPERATOR  
Drawer LL, Cortez, Colo 81321

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
660'FNL-660'FEL Sec 34 T32N R17W  
AT SURFACE: 5931  
AT TOP PROD. INTERVAL: 1762'  
AT TOTAL DEPTH: 1792


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:


TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☒  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐



(NOTE: Report results of multiple completion or zone change on Form 9-330.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We propose to remove the rods, pump and tubing. Run a string of 2 3/8" UP tubing with a packer set at 1750' and acidize through the tubing, through the 5" OD casingperfs at 1762'-1769' with Halliburton 15% acid, 1000 gallons and flush out tubing with approx. 8 BBLS water. We will then swab out all the spent acid and unset packer and pull same from well and run back in the tubing, pump and rods.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Office Manager DATE March 3-1982

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: MAR 11 1982

JAMES F. SIMS  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

ahz

NMOCC