

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 10-045-11265
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	7. Lease Name or Unit Agreement Name HUBBARD, LS 1015615
2. Name of Operator CONOCO INC 1005073	8. Well No. 2
3. Address of Operator 10 West 10th Ste 100 W, Midland, TX 79705	9. Pool name or Wildcat BLANCO MESAVERDE 472319
4. Well Location Unit Letter <u>E</u> : <u>1850</u> Feet From The <u>NORTH</u> Line and <u>900</u> Feet From The <u>WEST</u> Line Section <u>30</u> Township <u>32 N</u> Range <u>11 W</u> NMPM <u>SAN JUAN</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ADD MESA VERDE PERFS. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-7-94 MIBU. LOAD & TEST 4 1/2 X 7" ANNULUS TO 1000# HELD FOR 30 MIN. POOH W/ 2 3/8" TBG. GIH W/ 4 1/2" RBP SET @ 5295'. PERF CLIFFHOUSE/MENEFEE @ 4723-33, 4748-52, 4830-38, 4848-56, 4872-74, 4883-91, 4959-65 TOTAL OF 27 HOLES W/ 3 1/8" GUN. 1 SHOT EVERY OTHER FOOT. GIH W/ 2 1/8" TBG & PACKER SET @ 4615'. ADICIZE W/ 1800g 15% HCL W/ 54 BALL SEALERS GIH CLEAN OUT FILL. POOH W/ RBP. GIH W/ 2 3/8" TBG TO 5290'. HOOK WELL UP TO FLOWLINE. 11-23-94 RDMO. RETURN WELL TO PRODUCTION.

11-23-94 TEST: 44MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frank T. Krathly TITLE SR. REGULATORY SPEC. DATE 12-16-94
TYPE OR PRINT NAME FRANK T. KRATHLY TELEPHONE NO. 915-688-5424

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT #2 DATE DEC 19 1994
CONDITIONS OF APPROVAL, IF ANY: