

## SUNDRY NOTICES AND REPORTS ON WELLS

1. oil ☒ gas ☐ other

James P. Woosley

### 3. ADDRESS OF OPERATOR

P.O. Drawer 1480, Cortez, Colorado 81321

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2310' FNL & 965' FEL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

### TEST WATER SHUT-OFF

## FRACTURE TREAT

## SHOOT OR ACIDIZE

## REPAIR WELL

**PULL OR ALTER CASING**

**MULTIPLE COMPLETE**

## CHANGE ZONES

**ABANDON\***

(other)

SUBSEQUENT REPORT OF:

**RECEIVED**

SEP 23 1985

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

**BUREAU OF LAND MANAGEMENT**  
**FARMINGTON RESOURCE AREA**

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plan to plug and abandon well as follows weather permitting and rig availability:

1. Run 2-3/8" tubing to 1467' and fill hole with gelled mud.
2. Place plug from 1467' back to 1417' with 5.0 cu. ft. of neat slurry cement.
3. Shoot 4-1/2" casing off above cement behind casing and pull. 100' plug @ 8000
4. Run tubing and place plug from 100' back to surface with 10.87 cu. ft. of neat slurry cement.
5. Clean location.
6. Place proper plug and abandon marker.
7. Reseed location with recommended seed.

Subsurface Safety Valve: Manu. and Type

**18. I hereby certify that the foregoing is true and correct**

SIGNED [Signature] TITLE Office Manager DATE September 19, 1985

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

APPROVED  
AS AMENDED

SEP 26 1985

*John* M. MILLENBACH  
AREA MANAGER

**\*See Instructions on Reverse Side**

NMOCC