Aztec Oil & Gas Company  3. Address of Operator  P. O. Drawer 570, Farmington, New Mexico  4. Location of Well  UNIT LETTER M 990  South Line And 990  THE West Line, SECTION 10 TOWNSHIP 32N ANNEE 12W MMPM.  15. Elevation (Shaw whether DF, RT, GR, etc.)  6055 Gr  12. County  South Line And Plan Mesaverde - Dakota  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS  OTHER  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all portinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.									. 1	
DISTRIBUTION  SANTA FE		· · · · · · · · · · · · · · · · · · ·	<del></del>							
SANTA RE FILE   J. 6-1   J. 6-	NO. OF COPIES RECEIVED	1 -	2					Form C-103		
Substitute   1-45	DISTRIBUTION	DISTRIBUTION								
U.S.G.S. LAND OFFICE OPERATOR 3 SUNDRY NOTICES AND REPORTS ON WELLS  LOO NOT USE THIS PROPAGE TO PROPAGE TO SHALL BE TOOK OIL & GOES LOCASE NO.  TOO NOT USE THIS PROPAGE TO PROPAGE TO SHALL BE TO SEPTIMENT ASSESSMENT.  VILL		1/		NEW MEXICO						
State   Fom   State	FILE	1/1	4							
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS CONTROL OF STREET OF S		1						5a. Indicate Type		
DO NOT USE THIS FORWARD NOTICES AND REPORTS ON WELLS   DO NOTICE STANDING PRODUCT OF P		1						State	Fe	e X
2. Name of Operator  Nate   Gas Company   R. Form or Lease Name   Decker    3. Address of Operator   P. O. Drawer 570, Farmington, New Mexico   H. Line and   Policy   Peter from the    10. Township   32N   RANGE   12W   MAPPA.    11. Elevation (Show whether DF, RT, GR, etc.)   12. County    12. County   15. Elevation (Show whether DF, RT, GR, etc.)   12. County    15. Elevation (Show whether DF, RT, GR, etc.)   12. County    16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data    NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK   COMMENCE DRILLING OFNS.   CASING TEST AND CEMENT JOB    OTHER   OTHER   COMMENCE DRILLING OFNS.   CASING TEST AND CEMENT JOB    17. Describe Proposed or Completed Operations (Clearly state all partinent details, and give pertinent dates, including estimated date of storting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing    2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	OPERATOR	131						5. State Oil & Ga	is Lease No.	
2. Name of Operator  Nate   Gas Company   R. Form or Lease Name   Decker    3. Address of Operator   P. O. Drawer 570, Farmington, New Mexico   H. Line and   Policy   Peter from the    10. Township   32N   RANGE   12W   MAPPA.    11. Elevation (Show whether DF, RT, GR, etc.)   12. County    12. County   15. Elevation (Show whether DF, RT, GR, etc.)   12. County    15. Elevation (Show whether DF, RT, GR, etc.)   12. County    16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data    NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK   COMMENCE DRILLING OFNS.   CASING TEST AND CEMENT JOB    OTHER   OTHER   COMMENCE DRILLING OFNS.   CASING TEST AND CEMENT JOB    17. Describe Proposed or Completed Operations (Clearly state all partinent details, and give pertinent dates, including estimated date of storting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing    2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	(DO NOT USE THIS FO USE	SUN TM FOL	IDRY	NOTICES AND REPOSALS TO DELLE OR TO DEEPE	ORTS ON	WELLS BACK TO A DIFFERENT RESERVE	01R.			
Aztec Oil & Gas Company  3. Address of Operator  P. O. Drawer 570, Farmington, New Mexico  4. Location of Well  UNIT LETTER M 990  South Line And 990  THE West Line, SECTION 10 TOWNSHIP 32N ANNEE 12W MMPM.  15. Elevation (Shaw whether DF, RT, GR, etc.)  6055 Gr  12. County  South Line And Plan Mesaverde - Dakota  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS  OTHER  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all portinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	OIL GAS WEL							7. Unit Agreemen	t Name	****
3. Address of Operator P. O. Drawer 570, Farmington, New Mexico 4. Location of Well  UNIT LETTER M 990  FEET FROM THE South LINE AND 10. FIET FROM THE Mesaverde-Dakota  Mesaverde-Dakota  15. Elevation (Show whether DF, RT, GR, etc.)  6055 Gr  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK COMMENCE OBILLING OPNS.  CHANGE PLANS OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 105.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	2. Name of Operator					· · · · · · · · · · · · · · · · · · ·		8. Farm or Lease	Name	
P. O. Drawer 570, Farmington, New Mexico  4. Location of Well  UNIT LETTER M 990  FEET FROM THE SOUTH LINE AND 990  FEET FROM THE West LINE, SECTION 10 TOWNSHIP 32N RANGE 12W NMPM.  IS. Elevation (Show whether DF, RT, GR, etc.)  6055 Gr  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK COMMENCE DRILLING DRYS.  CHANGE PLANS CHANGE PLANS CHANGE PLUG AND ABANDONMENT COMMENCE DRILLING DRYS.  CASING TEST AND CEMENT JOB  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE BULE 1703.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	Aztec Oil & Ga	s Co	mpan	'n				Deck	ær	
A. Location of Well  WHIT LETTER M 990  PEET FROM THE SOUTH LINE AND 990  THE WEST LINE, SECTION 10 TOWNSHIP 32N RANGE 12W NMPM.  15. Elevation (Show whether DF, RT, GR, etc.)  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK COMMENCE OF ILLING OPHS.  CHANGE PLANS CHANGE PLANS  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.							·	9. Well No.		
UNIT LETTER M 990 FEET FROM THE SOUTH LINE AND 990 FEET FROM THE Messaverde - Dakota Messaverde - Dakota Messaverde - Dakota 10 Township 32N RANGE 12W MMPM.  15. Elevation (Show whether DF, RT, GR, etc.) 5055 Gr San Juan 12. County San Juan 12. County San Juan 13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of:  PERFORM REMEDIAL WORK TEMPORABILY ABANDON CHANGE PLUG AND ABANDONMENT COMMENCE ORILLing OPRS.  OTHER COMMENCE ORILLing OPRS.  CASING TEST AND CEMENT JOS OTHER COMMENT EST AND CEMENT JOS OTHER WORK) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.		70,	Farm	ington, New Mexi	co			# <u></u>	ł	
The West Line, Section 10 Township 32N RANGE 12W NAMPM.    15. Elevation (Show whether DF, RT, GR, etc.)   12. County San Juan   15. Elevation (Show whether DF, RT, GR, etc.)   12. County San Juan   16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of:    Perform Remedial work						· · · · · · · · · · · · · · · · · · ·		10. Field and Po	ol, or Wildcat	
The West Line, Section 10 Township 32N RANGE 12W NAMPM.    15. Elevation (Show whether DF, RT, GR, etc.)   12. County San Juan   15. Elevation (Show whether DF, RT, GR, etc.)   12. County San Juan   16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of:    Perform Remedial work	UNIT LETTER M		<del></del> .	990 FEET FROM THE _	Sout	1 LINE AND 990	FEET FROM	Mesaver	:de-Dakot	5a
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	•				-					
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	mmmmm	m	777	15. Elevation (She	ow whether	DF RT GR etc.)		10 Country	44444	444
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.								1		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing  2. Found corrosion hole in tubing at approximately 4928'.  3. Replaced 1 joint tubing.  4. Dressed Stinger and re-ran tubing.  5. Presently running Packer Test.	16.	Che	ck Ar	ppropriate Box To In	dicate I	lature of Notice Ren	ort or Oth	Doto		-1111
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	NOTIO	CE OI	FINT	ENTION TO:	1					
TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	PERFORM REMEDIAL WORK	]		PLUG AND ABA	INDON	REMEDIAL WORK	ΓX	ALTER	ING CASING	
OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	TEMPORARILY ABANDON	]				COMMENCE DRILLING OPNS.	Ħ			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	PULL OR ALTER CASING	]		CHANGE PLAN	5		<b>=</b>	7204 A	NO ABARDONME	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.  1. Pulled both strings of 1-1/2" tubing 2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.						OTHER				
<ol> <li>Pulled both strings of 1-1/2" tubing</li> <li>Found corrosion hole in tubing at approximately 4928'.</li> <li>Replaced 1 joint tubing.</li> <li>Dressed Stinger and re-ran tubing.</li> <li>Presently running Packer Test.</li> </ol>	OTHER									<del></del>
<ol> <li>Pulled both strings of 1-1/2" tubing</li> <li>Found corrosion hole in tubing at approximately 4928'.</li> <li>Replaced 1 joint tubing.</li> <li>Dressed Stinger and re-ran tubing.</li> <li>Presently running Packer Test.</li> </ol>	17. Describe Proposed or Co	mplete	d Oper	cations (Clearly state all pe	rtinent det	l ails, and give pertinent date	s, including	estimated date of :	tarting any p	roposed
2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	,			•						
2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.										
2. Found corrosion hole in tubing at approximately 4928'. 3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.	•				/011	•				
3. Replaced 1 joint tubing. 4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.							0001			
4. Dressed Stinger and re-ran tubing. 5. Presently running Packer Test.					bing a	t approximately 4	.928'.		•	
5. Presently running Packer Test.										
						g•				
TO THE PART OF THE	5. Pr	esen	tly	running Packer T	est.			•		
							<i>i.</i>			
				•					Th	
								Aug 20	107-	1

			OIL	CON. COM. DIST. 3
18. I hereby certify that the information above is true and complete the state of t	ete to the b	District Concrint and out	DATE_	August 26, 1970
CONDITIONS OF APPROVAL IF ANY:	TITLE _	SUPERVISOR DIST. 推り	DATE	AUG 2 8 1970