

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MOO-C-1420-1941

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UTE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

UTE-A

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 35, T-32N, R-16W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Cities Service Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1919, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface1980' FSL, 1980' FWL of Section, 35, T-32N, R-16W,
San Juan County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6665' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

T. D. 10,000' Lime. We will plug and abandon this well in the following manner:

50 SX Plug (150') 9802'-9962' across top of Mississippian at 9870'
50 SX Plug (150') 9145'-9295' across top of Barker Creek at 9282'
50 SX Plug (150') 8719'-8869' across top of Ismay at 8794'
50 SX Plug (150') 7700'-7850' across top of Hermosa at 7775'
50 SX Plug (150') 5973'-6123' across top of Dechelly at 6048'
35 SX Plug (100') 4505'-4605' across top of Entrada at 4555'
35 SX Plug (100') 3305'-3405' across top of Dakota at 3355'
50 SX Plug (100') 1350'-1450' 1/2 in and 1/2 out of 9 5/8" Casing at 1399'.
10 SX Plug (25') in top of 9 5/8" Casing 0'-25'
Install 4" dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Region Operation Mgr.

DATE

Jan. 3, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side