

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87418 (505) 334-6178 Fax (505)334-6170

GARY E. JOHNSON GOVERNOR

JENNIFER A. SALISBURY CABINET SECRETARY

December 16, 1996

Ms Dolores Diaz
Burlington Resources O&G Co
PO Box 4289
Farmington NM 87499

RE: Packer Leakage Retests

Dear Dolores:

Please find enclosed the inconclusive 1996 Packer Leakage Tests on the following wells:

San Juan 27-4 Ut #13 G-20-27N-04W 30-039-06992 San Juan 27-4 Ut #36 K-36-27N-04W 30-039-06810 Decker #4A O-10-32N-12W 30-045-23332

These wells need to be rescheduled and retested in a way that proves separation and shuts both zones in for a minimum of three days. Flow the higher pressured zone until the pressure decreases enough to determine if there is zone separation. Please notify this office a least 24 hours before tests are conducted so that we may provide a witness, and if you have any questions please feel free to call me at 334-6178.

Singerely,

**Ernest Cardona** 

Deputy O&G Inspector

EC/sh

**Encs** 

cc:

Well Files

**EC File**