Submit 3 Copies

APPROVED BY_

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico

Form C-103

	Energy, Minerals and Natural R	•	Revised 1-1-89
District Office DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 DISTRICT II	OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505		well api no. 30-045-24399
P.O. Drawer DD, Artesia, NM 88210	Santa 1 0, 11111	3	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			5. State Oil & Gas Lease No.
	ICES AND REPORTS ON WEL		
DIFFERENT RESEI (FORM C	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PEF -101) FOR SUCH PROPOSALS.)	RMIT"	7. Lease Name or Unit Agreement Name Montoya A 34
1. Type of Well: OIL GAS WELL WELL X	OTHER		
2. Name of Operator NERGEN RESOURCES CORPORATION	ON .		8. Well No. 1
3. Address of Operator 2198 Bloomfield Highway, Fat	rmington, NM 87401		9. Pool name or Wildcat Blanco MV/Basin DK
4. Well Location Unit Letter A : 900		Line and 700	Feet From The East Line
Section 34		ange 13W Ner DF, RKB, RT, GR, etc.)	MPM San Juan County
_	opropriate Box to Indicate NTENTION TO:	}	Report, or Other Data SEQUENT REPORT OF:
ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEN OTHER: Temporarily	ENT JOB
THER:		OTHER: _TCIIIDOT GT TT	7 Abandon Bakota
			- in-lading estimated data of stanting any proposed
 Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH with 	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 t h notched collar, 1 jt 2 3/	tds. tubing. RIH with How	co 4 1/2" CIBP on 2 3/8" tubing, set ting nipple, 149 jts 2 3/8" 4.7#
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH wit N-80 tubing. Landed at 1/17/00 RDMO.	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 t h notched collar, 1 jt 2 3/ 4713' ND BOP, NU wellhead.	tds. tubing. RIH with How /8" N-80 tubing, sea	co 4 1/2" CIBP on 2 3/8" tubing, set
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH with N-80 tubing. Landed at 1/17/00 RDMO. Also Does Not Meet the	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 t h notched collar, 1 jt 2 3/ 4713' ND BOP, NU wellhead.	tds. tubing. RIH with How /8" N-80 tubing, sea	co 4 1/2" CIBP on 2 3/8" tubing, set ting nipple, 149 jts 2 3/8" 4.7#
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH with N-80 tubing. Landed at 1/17/00 RDMO. (is Opes Not Meet the	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 t h notched collar, 1 jt 2 3/ 4713' ND BOP, NU wellhead.	tds. tubing. RIH with How /8" N-80 tubing, sea	co 4 1/2" CIBP on 2 3/8" tubing, set
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH wit N-80 tubing. Landed at 1/17/00 RDMO. As Does not meet the hot is APPRoved.	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 t h notched collar, 1 jt 2 3/ 4713' ND BOP, NU wellhead. Le ReQuike ments for Lok one Yeak	tds. tubing. RIH with How /8" N-80 tubing, sea	co 4 1/2" CIBP on 2 3/8" tubing, set ting nipple, 149 jts 2 3/8" 4.7#
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH wit N-80 tubing. Landed at 1/17/00 RDMO. As Does not meet the hot is APPRoved.	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 th notched collar, 1 jt 2 3/4713' ND BOP, NU wellhead. The ReQuike ments for John One Yeak To and Complete to the best of my knowled.	tds. tubing. RIH with How /8" N-80 tubing, sea Role 203, C,	co 4 1/2" CIBP on 2 3/8" tubing, set ting nipple, 149 jts 2 3/8" 4.7# JAN 2000
12. Describe Proposed or Completed Opwork) SEE RULE 1103. 1/13/00 MIRU. ND wellhe 1/14/00 POOH with total at 6680'. POOH. RIH with N-80 tubing. Landed at 1/17/00 RDMO. his Does Not Meet the hot in is AffRoved. Shut in Expires 1-1	ad, NU BOP. POOH with 60 st 217 jts 2 3/8" 4.7# N-80 th notched collar, 1 jt 2 3/4713' ND BOP, NU wellhead. The ReQuike ments for John One Yeak To and Complete to the best of my knowled.	tds. tubing. RIH with How /8" N-80 tubing, sea L Rule 203, C,	co 4 1/2" CIBP on 2 3/8" tubing, set ting nipple, 149 jts 2 3/8" 4.7# JAN 2000

_ TITLE _