UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-010989
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil G gas G	Fields
well well other	9. WELL NO.
2. NAME OF OPERATOR	le letti i ty∜
Tenneco Oil Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P. O. Box 3249, Englewood, CO 80155	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec. 29, T32N R11W
AT SURFACE: 1525' FSL 970' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6336' gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	医乳腺 动脉 医多种毒物 医卵巢囊囊
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING	Change on Form 5-550.)
CHANGE ZONES	20 kg 4 c c c c c c c c c c c c c c c c c c
ABANDON*	꼬의 씨 씨는 한 옷 사람들을 느린 사람들을 느蛋하다.
(other) Bradenhead squeeze	그게 느껴지어 주네는 위원병됐는 국민의 일본 등 사람이 되었다.
•	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally erilled, give subsurface locations and int to this work.)*
	그 그 그 그 그 그 그 사람들이 살아 그를 다고 했다.
4/6/82 - RIH w/bit and scraper and 2-3/8" tbg	. Tagged cmt @ 1120'. DO cmt. PT
CSG TO 2000 psi 15 mins - held ok. POOH w/tb	g. RIH w/retrieving head on 2-3/8"
tbg. Circ'd sd off RBP. Rolled hole w/1% KC	L wtr. Latched onto RBP and released
Well flwg quite a bit. Attempted to kill well	1, couldn't keep it dead. POOH w/23
strands. Left both sides flwg to pit overnight	
4/7/82 - Killed well w/1% KCL wtr. POOH w/tb	g and RBP. RIH w/tbg,
SN and pump out plug. Tagged sd @ 76	65'. CO w/foam to 7730'. Landed
tbg @ 7600'. Kicked well around w/N2. Left 1	FTCU. Will RDMOSU in the am.
,	
	the state of the s

Subsurface Safety Valve: Manu. a	nd Type	Set @	Pt.
18. I hereby certify that the foregon signed Denise Wilson	oing is true and correct	E4/12/82	
	(This space for Federal or State office use)		=
APPROVED BY	TITLE DA	TE	AGGEPTED FOR RECORD
		:	and the second s

*See Instructions on Reverse Side

NMOCO