Casing S Csg.Perf.		_w	Sx.	Int.	e		w	SpdCu. ftSx. PrProd. Stim.			.w	Cu. ft. Sx. T.		—e—	T Gas
.Р	BO/D _MCF/D A	ter	_Hrs.	SICP_		_PSI	After	Grav Days GOR		1st De					Å N S
Ojo Alamo	TOPS		NIĪD				Well Log		TEST DAT						
Kirtland			C-103			$\angle I$	Plat X		Schd.	PC	Q	PW	PD	D	Ref.No
Fruitland			C-104	·			Electric Log	1						<del>                                     </del>	1
Pictured Cliffs							C-122						<del>                                     </del>	┼	┼──
			Ditr				Dfa					<del> </del>		┼	┼──
Chacra			Datr				Dac					<del> </del>		├	<del> </del>
Cliff House			1.									ļ		ļ	<del> </del>
Menefee									<u> </u>			<del> </del>		<b></b> -	┼
Point Lookout									┝╼╼╁			-		<b></b>	├
Mancos									<del>  </del>		<u> </u>				ļ
Gallup															<u> </u>
Greenhorn															
Dakota															
Entrada															
							Δ.	oros 160 67				<b></b>			
					<del></del>			cres 162.67							Ĺ

Culpepper Martin #6 P-31-32N-12W

UNION TEXAS PETROLEUM CORP.

## Union Texas Petroleum



375 U.S. Highway 64 Farmington, New Mexico 87401 Telephone (505) 325-3587

June 17, 1986

Ms. Karen Baird New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec. NM 87410

Re: Culpepper Martin No. 6 Unit P-Section 31-T32N-R12W San Juan County, New Mexico

Dear Ms. Baird:

Pursuant to our conversation, Union Texas Petroleum (U.T.P.) requests that the Application for Permit to Drill this well be rescinded. Due to the current downturn in oil prices, U.T.P. is electing to drill this well at a later date.

If I may be of any further assistance, please advise.

Very truly yours,

Robert C. Frank Permit Coordinator

RCF:1mg



