
BURLINGTON RESOURCES

SAN JUAN DIVISION

May 10, 2000

Bureau of Land Management 1235 La Plata Highway Farmington, New Mexico 87401

Dear Sirs:



It is intended to change the surface hole size from 17 ½" to 14 ¾" and the surface casing from 13 3/8" to 11 ¾" 42# H-40 ST&C on the following wells. Depth interval will be at 0-200'.

Culpepper Martin #7C located 1185'FNL, 815'FEL, Sec. 28, T-32-N, R-12-W, Federal lease SF-078146.

Nordhaus #1B located 1170'FSL, 805'FWL, Sec. 13, T-31-N, R-9-W, Federal lease SF-078508.

Seymour #1B located 1797'FNL, 1085'FEL, Sec. 25, T-31-N, R-9-W, Federal lease SF-078505.

Seymour #3B located 2305'FSL, 2305'FEL, Sec. 24, T-31-N, R-9-W, Federal lease SF-078505.

Seymour #7B located 810'FNL, 1720'FEL, Sec. 23, T-31-N, R-9-W, Federal lease SF-078505.

Sunray A #1B located 915'FSL, 1880'FEL, Sec. 15, T-30-N, R-10-W, Federal lease SF-078125.

Sunray B #1B located 1690'FNL, 1775'FWL, Sec. 15, T-30-N, R-10-W, Federal lease SF-078125.

Sunray D #1M located 975'FNL, 765'FWL, Sec. 21, T-30-N, R-10-W, Federal lease SF-078204.

Sincerely,

Peggy Cole

Regulatory Supervisor

gar Cale

Ami dovolo