

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Simmons

8. Well No.

1

9. Pool name or Wildcat

Basin Fruitland Coal

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Meridian Oil Inc.

3. Address of Operator

PO Box 4289, Farmington, NM 87499

4. Well Location

Unit Letter F : 1960 Feet From The North Line and 1980 Feet From The West Line

Section 17 Township 30N Range 11W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5987' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: PB to Fruitland Coal ☐

03-21-89 MOL&RU. Blow well down. NU BOP. TOO H w/90 jts 1" pipe. PU
csg scraper. TIH w/61 jts 2 3/8" workstring to 1949'. CO
w/70 BW. TOO H w/scraper. TIH w/cmt. retainer to 155'.
Attempt to pull up & ret. sheared off. SDFN.
03-22-89 PU power swivel, bit, bit sub, DC's, swage & collar. TIH to
175'. Start drlg out cmt. ret. Run to 1985'. Tag btm. TOO H
w/tbg. TIH to 194' & work. TOO H w/scraper & LD. SDFN.
03-23-89 TIH w/cmt. ret set @ 1942'. Test tbg to 1000#. Stung thru
ret & displ. 25 sks. Class "B" neat cmt w/2% calcium
chloride down tbg. w/8 BW. Pull out of ret & rev. out
w/wtr. WOC. CO 12 BW. PT csg 2500#/20 min. TOO H. LD setting
tool. TIH on tbg. SD for weekend.
03-27-89 Spot 200 gal. acid across perf int. TOO H. Run CBL. Perf
1742-46', 1838-42' 8 spz; 1682-88' 12 shots; 1900-20' 40
shots; Pump 14,280 gal. gel & 18 tons CO2.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(cont'd on back)

SIGNATURE [Signature]

TITLE

Regulatory Affairs

DATE

4-24-89

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Original Signed by [Signature]

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

03-28-89 Flared gas. Unloaded well. Left flowing on choke. TIH 1050
CO. Tag TD @ 1942', no fill. Well open to atmosphere. SDF
03-29-89 Tag TD @ 1942'. No fill. CO to TD. TOOH w/tbg. TIH w/60 jt
2 3/8", 4.7#, J-55 EUE tbg to 1918' open ended. NU WH.
Released rig.