Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INTERI GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE* (Other instructions on reverse side)	Form approve Budget Burea 5. LEASE DESIGNATION Cont. 14-20-6	u No. 42-R1424. AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 1.			6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo 7. UNIT AGREEMENT NAME	
WE'L X WELL OTHER 2. NAME OF OPERATOR Skelly Oil Company 3. ADDRESS OF OPERATOR			8. FARM OR LEASE NAME Navajo "M" 9. WELL NO.	
Box 3360, Casper, WY 82602 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			1 10. FIELD AND POOL, OR WILDCAT Horseshoe-Gallup	
330' FSL & 330' FWL SW/4 SW/4			11. SEC, T., R., M., OR BLK. AND SURVEY OR AREA 33-T32N-R17W	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF 5350' DF	, RT, GR, etc.)	12. COUNTY OF PARISH	13. STATE NM
16.	Check Appropriate Box To Indicate N	lature of Notice, Report, or C	Other Data	<u>, , , </u>
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Temp 17. DESCRIBE PROPOSED OR CO proposed work. If we nent to this work.)*	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS DOPERATIONS (Clearly state all pertinen cell is directionally drilled, give subsurface local) I no longer produce from the cease for possible recomplet	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recompl t details, and give pertinent dates, tions and measured and true vertices	il depths for all markers	SING T* on Well m.)

JUN 1 5 1976

TEMPORARY ABANDONMENT EXPIRES JUN 1 1977

10 ha 10 1		
8. I hereby certify that the foregolds is true and coffect SIGNED	TITLE Area Superintendent	DATE 6/11/76
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE