

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Hospah Sand Unit
2. Name of Operator Tesoro Petroleum Corporation	8. Farm or Lease Name
3. Address of Operator 8520 Crownhill, San Antonio, Texas 78209	9. Well No. 14
4. Location of Well **UNIT LETTER <u>B</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>2711</u> FEET FROM THE <u>East</u> LINE, SECTION <u>1</u> TOWNSHIP <u>17N</u> RANGE <u>9W</u> NMPM.	10. Field and Pool, or Wildcat Upper Hospah Sand
15. Elevation (Show whether DF, RT, GR, etc.) 6964' GL	12. County McKinley

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:


REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

Squeeze Hospah Sand with sufficient volume of cement and displace to within 700' of the surface (approximately 893' plug). Will perforate at approximately 585' and pump sufficient volume of cement to fill annulus between casing and hole to surface, leaving tubing full of cement to surface. Will set 10' plug in top and install dry hole marker.

**This was originally filed as being 330' South of North Line and 2310' West of the East Line of NW/4. It was shown erroneously as being in the NW/4 rather than the NE/4.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. S. Hernandez TITLE Mgr. of Production Engineering DATE Sept. 21, 1971

APPROVED BY Ernest C. Amick TITLE Supt. Dist. III DATE 9-27-71
CONDITIONS OF APPROVAL, IF ANY: