

TENTATIVE CEMENTING PROGRAMS

Coal Creek Oil Co.
W.E. Duggen #2
H-20-29N-11W

Division-approved Plugging Program

Clean out hole to 700'

Set a cement plug 700' to 600' with 15 sacks of neat cement

Set a cement plug 150' to 50' with 30 sacks of neat cement

Set a top plug with 10 sacks of neat cement.

Fill pits, clean & level location

A dry hole marker will not be required

This hole is not cased.

All plugs will be a Class A,B or C cement with or without Cac12