

COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-403  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name C. Hare
9. Well No. 3
10. Field and Pool, or Wildcat
12. County San Juan

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Bloomfield Oil & Gas Co. Bedford, Inc. agent for State of New Mexico
3. Address of Operator P. O. Box E, Farmington, New Mexico 87401
4. Location of Well UNIT LETTER N 230 FEET FROM THE S LINE AND 1530 FEET FROM THE W LINE, SECTION 15 TOWNSHIP 29N RANGE 11W NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>


### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Oil Conservation Division has employed Bedford, Inc. to plug & abandon this well as follows:

1. Set plug from 706' to 550'
2. Perf @ 200' set plug from 200' to 100' inside & outside 6 5/8" casing
3. Set P & A marker & clean loc.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A. Bedford</u>	TITLE <u>Agent for State</u>	DATE <u>9-26-78</u>
APPROVED BY <u>AK Hendrick</u>	TITLE <u>SUPERVISOR</u>	DATE <u>NOV 29 1978</u>
CONDITIONS OF APPROVAL, IF ANY:		