

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>Francis L. Harvey</b>	8. Farm or Lease Name <b>Garrett</b>
3. Address of Operator <b>Box 990, Wichita Falls, Texas</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>J</b> <b>1735</b> FEET FROM THE <b>South</b> LINE AND <b>1655</b> FEET FROM THE <b>East</b> LINE, SECTION <b>12</b> TOWNSHIP <b>29N</b> RANGE <b>11W</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>5744 DF</b>	12. County <b>San Juan</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 9-14-67 this well was plugged and abandoned in the following manner:

60 sack cement plug was placed from 911 to 1401. Hole was filled with mud to surface and 5 sack plug was placed in top of surface casing and dry hole marker installed extending 4 feet above ground level. Location was leveled.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles W. Wilbur TITLE Agent for F.L. Harvey DATE 9-14-67  
APPROVED BY Ernest C. Jones SUPERVISOR DIST. #3 DATE SEP 15 1967  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_