APPLICATION FOR PLUGGING

	1. W. R. Webb		
	(hereinafter called "operator") is the operator of the		
	Fee #1 located		
	D-06-30N-11W		
	San Juan County, New Mexico. Well completed in 1935.		
	2. W. R. Webb as operator,		
has posted a (one well) (blanket) (cash) (surety) bo			
	the amount of NA in compliance with Section		
	70-2-14 N.M.S.A. 1978 and Rule 101 of the Rules and		
	Regulations of the Oil Conservation Division, which bond is		
	conditioned upon compliance with the Statutes of the State		
	of New Mexico and the Rules and Regulations of the Division		
	with respect to the proper plugging and abandonment of the		
	well(s) operated by said operator.		
(Alt. 1)	3. Not Applicable is surety on		
	said bond.		
(Alt. 2)	3 is holding savings		
	account No.		
(Alt. 3)	3. Operator has deposited with		

	the sum of \$	in Certificate
	of Deposit or savings account No.	
	assigned said account to the Oil Conser	
	security for said bond.	
(Alt. 1)	4. The Fee #! has	s not produced
	hydrocarbon substance for more than si	
	permit for temporary abandonment has be	
	operator or approved by the Division.	
(Alt. 2)	4. Operator has previously obtained a	n approved permit
	for temporary abandonment of said well,	but said permit and
	any extensions thereof has expired mor	e than six months
	prior to the filing of this applica	ation and the
	well has not p	roduced hydrocarbons
	since the expiration of said permit.	
	5. By virtue of the failure to o	btain production or
	to have an approved current temporary	abandonment permit,
	theFee #1	

presumed to have been abandoned.

6. By authority of Section 70-2-12 N.M.S.A. 1978, the Rules and Regulations of the Division require wells no longer productive or capable of production to be properly plugged.

7. Demand has been made upon the operator to either place said well to beneficial use or properly plug and abandon the same and the Operator has failed to do so.

WHEREFORE, The Supervisor of District Three of the Oil Conservation Division applies to the Director to enter an order:

- 2. Upon determination that said well should be plugged directing ______ w. R. Webb ______ as Operator (and ______ NA _____ as surety) to plug said ______ well within 45 days of the date of the Director's order.
- 3. Further ordering that if operator (or surety) fail to plug and abandon said well as ordered by the Director, that the Division be authorized to plug said well and to forfeit said bond, and further authorizing the Division to recover from the Operator any costs of plugging in excess of the amount of the bond.

	STATE NEW MEXICO
COUNTY San Juan	SEC. 6 T. 30N R 11W LOCATION 600 1/N 1000 1/W
FIELD OR AREA	LOCATION 600 1/N 1000 1/W
LEASE POO	WELL NO +
COMPANY W.R. Webb	SPD.9-28-34 COMPLETED 3-15-35
ELEV. 5760!	т. р. 1485! Р. в. 1410!
CASING 81 @ 8301	
SHOT OR ACID	
PERF.	
I.P. 15 bbls water	
PRODUCING FORM.	
PRODUCTIVE DEPTH OR INTERVAL	

REMARKS: