

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 March 4, 2004

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-30242
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B9312
7. Lease Name or Unit Agreement Name W. Dollarhide Queen Sand Unit
8. Well Number 120
9. OGRID Number 004115
10. Pool name or Wildcat Dollarhide Queen

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 Chaparral Energy, LLC

3. Address of Operator
 701 Cedar Lake Blvd., Oklahoma City, OK 73114


4. Well Location
 Unit Letter F : 1350 feet from the North line and 2435 feet from the West line
 Section 5 Township 25S Range 38E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)
 Pit Location: UL Sect Twp Rng Pit type Depth to Groundwater Distance from nearest fresh water well
 Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
 feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Maintain TA Status <input checked="" type="checkbox"/>	



13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

TD 3943', PBTD 3510', perms 3609'-3728', CIBP 3545'. Pressure test well to 600# for 40 min to demonstrate mechanical integrity 4/11/05.

This Approval of Temporary Abandonment Expires 4/11/10

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .

SIGNATURE Leigh Kuykendall TITLE Engineering Tech DATE 5/18/05

Type or print name Leigh Kuykendall E-mail address: leighk@chaparralenergy.com Telephone No. (405) 478 8770

(This space for State use)
 APPROVED BY Haydn W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 24 2005
 Conditions of approval, if any:

Statas Tisk
Chaparral Energy LLC
West Pollarhude Queen sand Unit #120
F. 5.25.38

Start PSI # 610
FIN PSI # 600
TIME 40min

NOON

11

10

9

8

7

6 A.M.

5

4

3

2

1

MIDNIGHT

11

10

9

8

BR 2221

4-11-05

SHAPIRO CONTROLS CORPORATION
FIELD SALES - NEW YORK

