	State of New Mexico		Form C-103		
Office District I Energy, Minerals and Natural Resources		May 27, 2004 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 District II		30-025-05285			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1000 Bio Broggs Bd. Artes NM 97410		STATE FEE X		
District IV Santa Fe, NIVI 8/303		5	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			168980		
	ICES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			J. M. Denton		
1. Type of Well: Oil Well	Gas Well Other		8. Well Number 11		
2. Name of Operator Brothers Production Company, Inc.			9. OGRID Number 2936		
3. Address of Operator			10. Pool name or Wildcat		
P.O. Box 7515, Midland, TX 79708		Denton (Wolfcamp)			
4. Well Location					
Unit Letter P: 330 feet from the South line and 990 feet from the East line					
Section 11	Township 15-S Range		NMPM	County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3785', DF 3800'					
Pit or Below-grade Tank Application	or Closure		RAIN ZOVERNO DA	gg 244 2000 to 19 millione 24 de 19 millione anno 19 millione anno 19 millione anno 19 millione anno 19 million	
Pit typeDepth to Groundy	aterDistance from nearest fresh water	r well Dist	ance from nearest surfa	ce water	
Pit Liner Thickness: mil					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK □ ALTERING CASING □					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A					
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
OTHER: OTHER: Temporarily Abandon 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.	ork). Old Roll 1103. 101 Maniple (Jon.p. 1.1.	.		
9-6-05					
1. MIRU pulling unit. OWU. Blow well down.					
1. MIRU pulling u	nit. OWU. Blow well do	wn.			
 MIRU pulling t NU BOP's. 	nit. OWU. Blow well do	wn.			
2. NU BOP's.	unit. OWU. Blow well down backer and POOH $w/2-7/8$ "				
 NU BOP's. Sting out of p 		tbg.	cmt on plug		
 NU BOP's. Sting out of p RU wireline. 	packer and POOH w/ 2-7/8"	tbg. . Dump 50'		•	
 NU BOP's. Sting out of p RU wireline. RU kill truck. 	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024'	tbg Dump 50' inhibited	water.		
 NU BOP's. Sting out of p RU wireline. RU kill truck. Pressure up ca 	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold	tbg. Dump 50' inhibited for 30 min.	water.		
 NU BOP's. Sting out of p RU wireline. RU kill truck. 	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold:	tbg. Dump 50' inhibited for 30 min. of Temporar	water.	SII AUG	
 NU BOP's. Sting out of p RU wireline. RU kill truck. Pressure up ca 	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold	tbg. Dump 50' inhibited for 30 min. of Temporar	water.) SII Allo	
 NU BOP's. Sting out of p RU wireline. RU kill truck. Pressure up ca 	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold:	tbg. Dump 50' inhibited for 30 min. of Temporar	water.	SII wised	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck. 6. Pressure up ca 7. RD kill truck.	Packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold : This Approval C Abandonment E	tbg. Dump 50' inhibited for 30 min. Temporar Expires	water. y 9/9/18	SII alls no ived	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck. 6. Pressure up ca 7. RD kill truck.	packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold:	tbg. Dump 50' inhibited for 30 min. Temporar Expires	water. y 9/9/18	r certify that any pit or below-	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck. 6. Pressure up ca 7. RD kill truck.	Packer and POOH w/ 2-7/8" RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a second control of the c	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledg	water. y 9/9/18	r certify that any pit or below-	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck 6. Pressure up ca 7. RD kill truck I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a supplementations of the control of th	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledge a general permit duction Sup	water. y 9/9/18 ge and belief. I further or an (attached) alternate operintendent	r certify that any pit or below- tive OCD approved plan 12. DATE 9-19-05	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck 6. Pressure up ca 7. RD kill truck I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Danny	RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a supplementations of the control of th	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledge a general permit duction Sup	water. y 9/9/18 ge and belief. I further or an (attached) alternate operintendent	r certify that any pit or below- tive OCD approved plan 12. DATE 9-19-05	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck 6. Pressure up ca 7. RD kill truck I hereby certify that the information grade tank has been/will be constructed of SIGNATURE	RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a supplementations of the control of th	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledge a general permit duction Sup	water. y 9/9/18 ge and belief. I further or an (attached) alternate operintendent	r certify that any pit or below- tive OCD-approved plan DATE 9-19-05 lephone No. 432-682-2516	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck 6. Pressure up ca 7. RD kill truck I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name For State Use Only APPROVED BY:	RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a supplementations of the control of th	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledge a general permit duction Sup	water. y 9/9/18 ge and belief. I further or an (attached) alternate operintendent	r certify that any pit or below- tive OCD approved plan 12. DATE 9-19-05	
2. NU BOP's. 3. Sting out of p 4. RU wireline. 5. RU kill truck 6. Pressure up ca 7. RD kill truck I hereby certify that the information grade tank has been/will be constructed of signal tank has been signal	RIH and set CIBP @ 9024' Load hole w/ corrosion asing to 500 psig. Hold: This Approval of Abandonment for above is true and complete to the best reclosed according to NMOCD guidelines [], and a supplementations of the control of th	tbg. Dump 50' inhibited for 30 min. of Temporar expires of my knowledge a general permit duction Sup	water. y 9/9/18 ge and belief. I further or an (attached) alternate operintendent	r certify that any pit or below- tive OCD-approved plan DATE 9-19-05 lephone No. 432-682-2516	

