Sabmit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30-025-12279 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X
District IV - (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
1. Type of Well: Oil Well	Gas Well X Other Injection	HOBBS OCD	8. Well Number 51
2. Name of Operator CHEVRON	U.S.A. INC.	OCT 2 9 2015	9. OGRID Number 4323
3. Address of Operator 15 SMITH	ROAD MIDLAND, TX 79705		10. Pool name or Wildcat
		RECEIVED	DOLLARHIDE TUBB DRINKARD
4. Well Location		1120-	
Unit Letter: H 2310 feet from the NORTH line and 330 feet from the EAST line			
Section 31 Township 24S Range 38E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12 Check	Appropriate Box to Indicate N	Nature of Notice	Penort or Other Data
12. Check 7	appropriate Box to indicate i	valure of Notice,	Report of Other Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: REPAIR AND OBTAIN PASSING CHART OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
proposed completion of rec	ompietion.		
			IIT 10/31/2015. MAXEY G. BROWN HAS A CHEVRON'S ENGINEER ON JOB
CHEVRON PLANS TO ADD PER PLAN TOP PERF @ 5980 IN THE PACKER DEPTH CHANGE PROP OBTAIN A PASSING CHART; RETURN WELL TO INJECTION	TUBB RESERVOIR PROPERTY		
Spud Date:	Rig Release D	Date:	
I hereby certify that the information	above is true and complete to the h	best of my knowledge	e and belief.
SIGNATURE	TITLE: REGUL	ATORY SPECIALIS	DATE: 10/27/2015
Type or print name: DORIAN K. FU For State Use Only	JENTES E-mail address: I	DJVO@CHEVRON.	<u>COM</u> PHONE: 432-687-7631
APPROVED BY: Maley Conditions of Approval (if any):	Shown Street Di	et Superior	DATE 12/1/2015

DEC 0 2 2015

WDDU 51 WELLBORE DIAGRAM CURRENT

Well No: 51 FORMATION: TUBB, DRKD, ABO FIELD: West Dollarhide Drinkard Unit GL: 3144 CURRENT STATUS: WIW LOC: 2310' FNL & 330' FEL Sec: 31 TOWNSHIP- 24S Cnty: Lea KB: API NO: 30-025-12279 DF: Chevno: FB3220 RANGE: 38E State: NM Date Completed: 9/11/52 Initial Production: Initial Formation: Lwr Drkd/ Abo 288 BO - Mcf. 0 BW Flow 16" 65# csg set @ 161' w/ 125 sx, circ FROM: 6325' TO: 6486 GOR, - Sp Grv Hole Size: 20' Initial completion: Open hole completion: 6325-6486' Subsequent workovers: 03/55: Acid Frac w/ 20k gal 11/69: Convert to injection 07/73: Deepen to 6812', Run 5" liner 6087-6812' Perf 6410-6728' (gross - lwr DRKD and ABO) and acidz w/ 10k gal 15% NE 6k lbs salt 11/77: Sqz 7" csg hole: Locate hole in 7" csg 5967-98'. Set plug @ 6025'.Cmt holes w/ 400 sx cmt. Drld out cmt & well started water flow @ 1 GPM. Set CMR @ 5784'. Cmt w/ 300 sx. D/O cmt. SI to wait for AFE to run liner. 12/84: Tie back 5" liner: TiH w/ 5" RBP, wouldn't set @ 6100'. Kept going DH, RBP would go down but not up. Cut tbg @ 6090'. Recovered 7" pkr & retrieving tool. Fish & recover RBP. Set 5" CIBP @ 6230'. Tie in 5" liner to existing liner. Run to surface. Cmt w/ 500 sx. D/O cmt & CIBP to 6431'. Mill to 6448', rec'd scale. cast iron, csg & rubber. Tag tight spot @ 6420', work through, tag 6448' make no hole. POOH w/ WS, DC's and bit; left 1 cone in hole. Dress tight spot at 6420'; circ clean. RTI. TOC: 2640' (T.S.) 06/00: Repair csg & Acdz: POOH w/ tbg in pieces (correded & covered in scale). Tag fill @ 6361', Set RBP @ 6244'- csg OK, wtr flow coming from DRKD perfs. C/O scale & iron sulfide 6361-6455'. Hung up mill- maybe outside csg. Acdz DRKD perfs w/ 3000 gal 15% & 1000# GRS. Set inj pkr @ 6247'. RTI. 05/2010 Repair Comm: Mill thru tight spot @ 6420'. Mill on junk & scale 6450-6595'. Returns mostly iron sulfide w/ some sttel & rubber pieces. Tag hard @ 6775', mill to 6790'. WS stuck, parted near surface. POOH w/ WS, left mill & 2 DC's in hole. TOF @ 10-3/4" 40# csg set @ 3009' w/ 2500 sx, circ Hole Size: 13-3/4" 6760'. Fishing tools get stuck, lose screw-in sub, bump jars, oil jars, XO & 3 DCs. New TOF @ 6,606'. Wash down to 6776' (several pieces of csg in WP). RECOVER ALL FISH. Perf 6334-6406'. Acdz w/ 4000 gal 15% w/ 2500# GRS. No tag, well clean to 6730'. Well has collapsed csg @ surface or WH issues. Leave well Sl. 01/2011: POOH w/ tbg, set RBP's. Cut off WH & csg, weld on new csg & WH. Release RBPs. Set inj pkr @ 6261'. **Tubing Strings** Rannad Run ng - Production Casing Repair, 1/17/2011 06:30 2/7/2011 1 Tubing,TK-99 IPC 2 3/8 1.867 1 Tubing,TK-99 IPC 23/8 1.867 98 Tubing,TK-99 IPC 23/8 1.867 4.70 4.06 4.70 C-90 4.70 C-90 198 Tubing,TK-9 On-OffTool TOC: 5400' Hole in 7" csg @ 5967-98'; Cmt w/ 700 sxs (10/77) TLA 5.5" Liner Adapter @ 6075' (7/73) X X Proposed Perfs: Tubb: 5980'-89', 6050'-79', 98'-6122', 85'-6208', 28'-39', 98'-6316' w/ 4 SPF, 120 deg. (115 net ft) Upr DRKD (05/10): 6334-40', 52-58', 74-90', 98-6406' w/ 4 JSPF. 7" 20 & 23# csg set @ 6325' w/ 400 sx, TOC @ Tight spot @ 6420' 2640' by T.S. LWT DRKD & ABO (07/73): 6410-23', 27-32', 42-46', 54-66', 70-82', 6529-39', 77-94', Hole Size: 8-3/4" 6632-38', 41-50', 90-96', 6720-28' w/ 1 spf *5" 13# Liner 6087-6812' (7/73) Open Hole 6325-6486' (9/52) *5" ??# Liner 6082'-surf (12/84) cmt w/ 500 sx, DNC, TOC: TD: 6812 Last Checked

PBTD: 6730'

10/26/2015 J. Daraje

5400' by TS