State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

Tony Delfin Deputy Cabinet Secretary David Catanach, Director Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

12-May-16

BURGUNDY OIL & GAS OF N M INC 401 W TEXAS STE 1003 MIDLAND TX 79701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

A Real Bar	al a company		INSPECTION	V DETAIL	SECTION		·
STATE VACUUM UNIT No.010 Inspection Date Type Inspection			Inspector	Violation?	H-32-17S-34E *Significant Non-Compliance?	30-025-02169-00 Corrective Action Due By:	-00 Inspection No.
05/12/2016	Routine/Perio Violations Surface Damage		Mark Whitaker	Yes	No	8/15/2016	iMAW1613360877
Comments	on Inspection:	marker has c CORRECT M	LEASE BONDS. Lease onduit riser and meter d MARKER. NEED TO F D TO REMOVE OR CO	lisconnect . F REMOVE CO	iles of dirt on 3 sides ONDUIT RISER AND	of location. NEED T DISCONNECT FR	°O OM

STATE VA Inspection Date	CUUM UNIT N Type Inspection		Violation?	G-32-17S-34E *Significant Non-Compliance?	30-025-02171-00-0 Corrective Action Due By:	0 Inspection No.
05/12/2016	Routine/Period Violations Surface Damage/I		Yes	No	8/15/2016	iMAW1613358757
Comments of	on Inspection:	DO NOT RELEASE BONDS. Lease side of location. 1 wire rope anchor of marker. NEED TO CORRECT MAR NEED TO REMOVE INJECTON RI DISCONNECT INJECTION LINE A	on SW corne KER, REMO SER 2 FOO	r of location. Injection OVE ANCHORS, AN T BELOW GROUNI	n riser and old well sig ND REMOVE WELL S	n by
STATE VA	CUUM UNIT N	No.013		K-32-17S-34E	30-025-02175-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/12/2016	Routine/Period Violations Surface Damage/I		Yes	No	8/15/2016	MAW1613359864
Comments of	on Inspection:	DO NOT RELEASE BONDS. 1 stee concrete poured base. Power pole cut next to marker. NEED REMOVE AN CONCRETE. NEED TO CUT POWI REMOVE INJECTON RISER 2 FOO INJECTION LINE AT STATION.	t off 1 foot a NCHOR. NE ER POLE O	bove ground level NV ED TO CUT BOLTS FF BELOW GROUN	V of marker. Injection OFF FLUSH WITH D LEVEL. NEED TO	riser

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, Mark Whitelen Petroleum Engr, Specialist

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240



BURGUNDY OIL & GAS OF NM INC 401 WEST TEXAS SUITE 1003 MIDLAND, TX 79701

魔3 .