Submit I Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			Revised July 18, 2013 WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 8821640BBSIL CONSERVATION DIVISION			3002544210	
District III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Azzec, NM 87410 District IV - (505) 476-3460 SEP 2 7 2010 Santa Fe, NM 87505			5. Indicate Type of Lease STATE FEE	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
SUNDRY NOTAES AND REPORTS ON WELLS			E-1639 7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			WEST EUMONT UNIT	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTOR			8. Well Number 214	
2. Name of Operator			9. OGRID Nu 371416	mber _
FORTY ACRES ENERGY, LLC 3. Address of Operator			10. Pool name or Wildcat	
11777B Katy Freeway, Suite #305, Houston, TX 77079			EUMONT: Yates-Seven Rivers-Queen (Oil)	
4. Well Location Unit Letter B: 2485 feet from the North line and 1335 feet from the East line Section 2 Township 21S Range 35E NMPM LEA County				
Section 2 Township 21S Range 35E NMPM LEA County				
	11. Elevation (Show whether DR, 3563' GR	, RKB, RT. GR, etc.)	:	The Kingson of the Control of the Co
1 3303 UK				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL				ALTERING CASING D
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗆	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER: STEP RATE TEST		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
The well is injecting approximately 275 bpd at 760 psi on the surface. Following results of the step rate test, it is expected these wells will inject 500-700 bpd.				
Shut wells in 48 hours prior to conducting the step rate test.				
 Using a pump truck equipped with a chart recorder, begin injecting at a gradient of 0.05 psi/ft. Increase the gradient to 0.1, 0.2, 0.3, 0.4 and 0.5 psi/ft or until Formation Parting Pressure is reached. 				
4. A surface pressure vs. rate and bottom hole pressure vs. rate charts will be supplied to the OCD following the tests.				
PROVIDE S.R.T. RESULTS				
TO SANTA FE OCD FOR				
Spud Date:	APPRO'	VAL		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE TITLE Geologist DATE 09/13/2018				
Type or print name <u>Jessica LaMarro</u> E-mail address: <u>jessica@facnergyus.com</u> PHONE: <u>832-706-0041</u> For State Use Only				
APPROVED BY:	Accepted for BILE			DATE
APPROVED BY: Accepted for Record Only Conditions of Approval (if any): DATE Only O				
Managemic Aliginas				





