

| Submit 1 Copy To Appropriate District Office   | State of New Mexico                    |  | Form C-103   |
|--|--|--|--|
| District I - (575) 393-6161  | Energy, Minerals and Natural Resources |  | Revised July 18, 2013  |
| 1625 N. French Dr., Hobbs, NM 88240  |  |  | WELL API NO.   |
| <u>District II</u> – (575) 748-1283<br>811 S. First St., Artesia, NM 88210   | OIL CONSERVATION DIVISION              |  | 30-025-42461   |
| District III - (505) 334-6178  | 1220 South St. Francis Dr.             |  | 5. Indicate Type of Lease  STATE  FEE  |
| 1000 Rio Brazos Rd., Aztec, NM 87410<br><u>District IV</u> – (505) 476-3460  | Santa Fe, 1                            | NM 87505   | 6. State Oil & Gas Lease No.   |
| 1220 S. St. Francis Dr., Santa Fe, NM  | ,                                      |  | o. State on & das Lease No.  |
| 87505  | TICES AND REPORTS ON                   | WEIIC  | 7. Lease Name or Unit Agreement Name   |
| (DO NOT USE THIS FORM FOR PROPO  | OSALS TO DRILL OR TO DEEPER            | 16 BB B B (C) (C) (C)                                  | 7. Dease Name of One Agreement Name  |
| DIFFERENT RESERVOIR. USE "APPL"  | LICATION FOR PERMIT" (FORM C           | C-101) FOR SUCH  | Wild Cobra 1 State SWD   |
| PROPOSALS.)  1. Type of Well: Oil Well   | Gas Well  Other                        | NOV 0 9 2018   | 8. Well Number 2   |
| 2. Name of Operator  | Gas wen Onler                          | 2010   | 9. OGRID Number  |
| COG Operating LLC  |  | RECEIVED   | 229137   |
| 3. Address of Operator   |  |  | 10. Pool name or Wildcat   |
| 2208 W Main Street, Artesia,   | NM 88210                               |  | SWD; Dev-Fuss-Mon-Simp-Ell   |
| 4. Well Location   |  |  |  |
| Unit Letter <u>C</u> ; 660 feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line  |  |  |  |
| Section 1  | Township 19S                           | Range 34E  | NMPM Lea County  |
| A STATE OF THE STA | · ·                                    | her DR, RKB, RT, GR, etc. <sub>/</sub><br><b>5' GR</b> |  |
| ALC: The second  |  | <del>o orc</del>                                       | The state of the s |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   |  |  |  |
| 12. Check  | rippropriate Box to man                | edic ratare or rectice,                                | report of other Data   |
|  | NTENTION TO:                           |  | SEQUENT REPORT OF:   |
| PERFORM REMEDIAL WORK  | <del>-</del>                           | REMEDIAL WOR   | <del>-</del>   |
| TEMPORARILY ABANDON  | <del>-</del>                           |  | <del></del>  |
| PULL OR ALTER CASING   |  | CASING/CEMEN   | T JOB  |
| DOWNHOLE COMMINGLE   |  |  |  |
| CLOSED-LOOP SYSTEM  OTHER:   | _                                      | OTHER:   | П  |
|  | apleted operations. (Clearly st        |  | d give pertinent dates, including estimated date   |
| of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of   |  |  |  |
| proposed completion or recompletion.   |  |  |  |
|  |  |  |  |
| 1. MIRU WSU and pull work string and packer.   |  |  |  |
| 2. Retrieve RBP at 14700'. Set 7" composite bridge plug just above permanent packer at 14746'.   |  |  |  |
| 3. Run 5.5"/20ppf/P110/Flush Joint liner to be set from 9500' to 14740', tag composite plug, cement with 250 CF Class  |  |  |  |
| H cement with additives, set liner hanger and circulate excess cement off top of liner hanger.   |  |  |  |
| 4. Dress off top of liner hanger, pressure test liner top, drill out liner float assembly and drill out composite plug   |  |  |  |
| between liner shoe and original 7" permanent injection packer.   |  |  |  |
| 5. Run cement bond log across liner.   |  |  |  |
| 6. Set 5.5" CRA permanent injection packer at approximately 14730'. Run approximately 5330' 3.5"/10ppf/L80/EUE   |  |  |  |
| Special Clearance fiberglass lined injection tubing plus approximately 9400' 4.5"/13.1ppf/P110/BTC fiberglass lined  |  |  |  |
| injection tubing.  |  |  |  |
| 7. Place inhibited packer fluid inside the tubing x casing annulus and latch into packer. Install injection tree.  |  |  |  |
| 8. Notify NMOCD and run MIT on tubing x casing annulus (500 psi for 30 minutes).   |  |  |  |
| <ol><li>Return well to injection</li></ol>   | n service.                             |  |  |
|  |  |  |  |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief.   |  |  |  |
| $(1, 1, \dots, 1)$   |  |  |  |
| SIGNATURE  | TITLE_                                 | Regulatory Analyst                                     | DATE November 6, 2018  |
| Town or maint your Date Vis  | Coodles E 1 1 1                        | hanadlas@ss=sh= ===                                    | DUONE, 575 740 6050  |
| Type or print name Bobble JG For State Use Only  | E-mail address:                        | bgoodloe@concho.cor                                    |  |
| To State Ost Only  | // _                                   | mateal8i   | DATE 11/59/18  |
| APPROVED BY:   | TITLE                                  | <b>E</b> Grorer  | DATE ///09/18  |

APPROVED BY:
Conditions of Approval (if any):





Wild Cobra 1 State SWD 2