Form 3160-5 (April 2004)

1075 M. Franch Drive UNITED STATES Makaba, NVA 88240

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

Do not use th	NOTICES AND REI nis form for proposals t ell. Use Form 3160-3 (a	o drill or to re-	enter an	6. If Indian,	Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Gas Well Other					7. If Unit or CA/Agreement, Name and/or No.	
2. Name of Operator UHC New M 3a Address P.O. Box 450 Artesia, NM 4. Location of Well (Footage, Sec.,	3b. Phone No. (include area code) 505-746-4448 60 feet from the East Line		8. Well Name and No. Cone Federal 4 4 9. API Well No. 30-041-20450 10. Field and Pool, or Exploratory Area Tomahawk San Andres 11. County or Parish, State Roosevelt N.M.			
	PPROPRIATE BOX(ES) TO		· - · · · · · · · · · · · · · · · · · ·	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	TYI Deepen Fracture Treat New Construction Plug and Abandon Plug Back	PE OF ACTION Production (Statement of the Complete of Temporarily About the Complete of the C		Water Shut-Off Well Integrity Other Remedial workover	
Attach the Bond under which the following completion of the inv	ctionally or recomplete horizontally ne work will be performed or provi- colved operations. If the operation is nal Abandonment Notices shall be the	y, give subsurface location de the Bond No. on file w results in a multiple comp	ns and measured and true rith BLM/BIA. Require letion or recompletion in	e vertical depths d subsequent re a new interval,	of all pertinent markers and zones. ports shall be filed within 30 days a Form 3160-4 shall be filed once	

MIRU. RIH w/ notch collar, bailer and tbg, tag @ 2622' 79 jts. Turn on tbg, would not tork up. POOH standing back tbg found what appears to be a salt plug in the csg. Pumped 13 bbls of fresh water dwn csg. Preparing to break through w/3 7/8" bit in the morning. Secure well and shut dwn.

10-11-06 RIH with 3 7/8" bit and tbg, tag @ 2622'. Start turning on tbg drill, dwn 12' to 2634'. Cannot make anymore hole. Pump 15 bbls of fresh water dwn hole. Turn on tbg again cannot make any hole. POOH w/ tbg and bit. RIH w/ spear and tbg, tag @ 2634', turn on tbg, cannot latch on to fish. POOH w/ tbg and spear. RIH w/ impression block and tbg, tag @ 2634' POOH w/ tbg and impression block. RIH open ended w/ tbg, POOH laying dwn tbg. Secure well. Rig dn.

		<u>/å</u>	32021222324262
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	l	28	sqq ₀ H
Ronnie Grado (rgrado@lothian.us)	Title Production Tech	9131	Peceived
Signature	Date 10-30	- OF A	900 ₀₀ (5)
ACCEPTED FORHERE PARE FOR FEDE	RAL OR STATE OFFIC	E USE	7110. E
Approved by S are attarned proprovary in horized does no	Title	Date	687934
Conditions of approval, there are attached the proval of this hotice does no certify that the applicant holds legal or equitable title to those rights in the su which would entitle the applicant to conduct operations thereon.	t warrant or bject lease Office		
Title 18 U.S.C. Section 1001 and Title 33 U.S.C. Section 1212, make it a crime States any also, fictitious or Paneluleht States any also, fictitious or Paneluleht States and States any also, fictitious or Paneluleht States and Stat	for any person knowingly and willfu y matter within its jurisdiction.	lly to make to any department or	agency of the United
(Instructions on many 2)			

GWW