

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 87240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 May 27, 2004

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br>30-025-38524  |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name:<br>North Hobbs G/SA Unit                                      |
| 8. Well Number<br>628   |
| 9. OGRID Number<br>157984   |
| 10. Pool name or Wildcat<br>Hobbs; Grayburg - San Andres  |

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 Oil Well  Gas Well  Other

2. Name of Operator  
 Occidental Permian Limited Partnership

3. Address of Operator  
 P.O. Box 4294, Houston, TX 77210-4294

4. Well Location  
 Unit Letter B : 290 feet from the North line and 2510 feet from the East line  
 Section 19 Township 18-S Range 38-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
 3663' GR

Pit or Below-grade Tank Application  or Closure

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON

TEMPORARILY ABANDON  CHANGE PLANS

PULL OR ALTER CASING  MULTIPLE COMPLETION

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING

COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

OTHER: Spud & Run Surface Casing

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attachment



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines  , a general permit  or an (attached) alternative OCD-approved plan

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 12/18/06  
 E-mail address: Mark\_Stephens@oxy.com  
 Type or print name Mark Stephens Telephone No. (713) 366-5158

For State Use Only  
 APPROVED BY Larry W. Wink TITLE OG FIELD REPRESENTATIVE II/STAFF MANAGER DATE DEC 26 2006  
 Conditions of Approval, if any

12/15/06: MI x RU. Spud 12-1/4" hole at 3:00 a.m. (NMOCD notified)

12/15/06 -

12/18/06: RU casing crew. Run 37 jts. 8-5/8", 24#, J-55, ST&C casing with 11 centralizers and set at 1518'. RU Halliburton and cement with 500 sx. Premium Plus (lead) and 300 sx. Premium Plus (tail). Circulate 251 sx. to surface. WOC. Cut off casing and weld on wellhead. NU BOP stack. Test BOP, choke manifold, and hydril. Pressure test casing to 1000 psi x 30 min. Drill out cement and float equipment and resume drilling operations.