Submit 3 Copies To Appropriate District	State of New Me			Form C-103
Office District I	Energy, Minerals and Natur	al Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	
District II	OIL CONSERVATION DIVISION		30-025-09251	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗴	FEE 🗆
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	· · · · · · · · · · · · · · · · · · ·	2232426	6. State Oil & Gas Leas	e No.
SUNDRY NOTIC	ES AND DEBORTS ON WEI	10	7 Lana Name 1 1 1 1 1 1 1 1 1	A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO SEEPEN OR HOUSE BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) PROPOSALS.) DONIES OF THE PROPOSALS.			7. Lease Name or Unit	Agreement Name:
1. Type of Well: Oil Well X Gas Well			8. Well Number	
2. Name of Operator	13	T	9. OGRID Number	
CIMAREX ENERGY CO. OF COLO	RADO ATIN: ZENO FARRI			
3. Address of Operator			10. Pool name or Wildcat	
P.O. BOX 140907, IRVING, TEXAS 75014-0907			JALMAT-TNSL-YATES-7RV	
4. Well Location				
Unit Letter:	1650 feet from the SO	IH line and	990 feet from the	eEAST line
Section 04	Township 23S	Range 36E	NMPM Co	ounty LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,497' GR				
Pit or Below-grade Tank Application or Closure 🛛				
Pit type STEE; Depth to Groundwater 220' Distance from nearest fresh water well * Distance from nearest surface water *				
Pit Liner Thickness: mil	Below-Grade Tank: Volume.	bbls: Construction	on Material *NONE WITHI	N 1,000'
NOTICE OF INTERPERSON TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	SUB REMEDIAL WORK COMMENCE DRILL	SEQUENT REPOR AL NG OPNS. PI	
PULL OR ALTER CASING	MULTIPLE L	CASING TEST AND CEMENT JOB		
OTHER:		OTHER: Approv	ed as to plugging of th	e Well Bore.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including the standard of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram or recompletion.				
	100'; MIX & PUMP A 30 SX. O# BRINE W/ 25#GEL/BBL.	OMT. PLUG ON TOP (OF CIBP @ 3100'.	
12/20/06: MIX & FUMP A 50	SX. CMT. PLUG @ 1600'-140	0'.		
MIX & PUMP A 30	SX. CMT. PLUG @ 540'; WOO	- DID NOT TAG OM	PLUG.	
12/21/06: MIX & FUMP A 30 SX. CMT. PLUG @ 540'; WOC & TAG TOP OF CMT. PLUG @ 400'.				
	SX. CMT. PLUG @ 270'; WOO			
	SX. CMT. SURF. PLUG @ 63'	-3'; Weld Steel Pi	ATE ON CSG. & INSTALL	DRY HOLE MARKER
WELL PLUGGED AN	DABANDONED ON 12/21/06.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan				
SIGNATURE	TIT			TE01/04/07
Type or print name DAVID A. EYLE	E-r		DEYLER@MILAGRO-RES.CX	
For State Use Only				
APPROVED BY Harry	Wind	ESNAMA TO	DATI	JAN 1 0 2007
Conditions of Approval, if and:				