Submit 3 Copies To Appropriate District Office District I		lew Mexico	Form C-103
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. /
1301 W. Grand Ave., Artesia N	CEIVE CONSERVA	ATION DIVISION	30-025-11720 / 5. Indicate Type of Lease
District III	1220 South S	St. Francis Dr.	STATE FEE S
1000 Rio Brazos Rd., Aztec, NM 87410	:B 05 2009 Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe,	MBSOCD		
87505 SLINDRY NO	OTICES AND REPORTS ON	WELLO	
(DO NOT USE THIS FORM FOR F	PROPOSALS TO DRILL OR TO DEE APPLICATION FOR PERMIT" (FOR	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT
1. Type of Well: Oil Well	☑ Gas Well ☐ Other	<del>-</del>	8. Well Number E-22 /
2. Name of Operator L	EGACY RESERVES OPERA	TING LP	9. OGRID Number 240974
Address of Operator P	.O. BOX 10848		/
M	IDLAND, TX 79702		10. Pool name or Wildcat JUSTIS-BLINEBRY-TUBB-DRINKARD
4. Well Location			
Unit LetterM:_	660feet from the6	SOUTH line and	990feet from theWESTline. /
Section 24	Township T25S	Range R37E	NMPM LEA County V
	3070' GL	ether DR, RKB, RT, GR	, etc.)
Pit or Below-grade Tank Application	· · · · · · · · · · · · · · · · · · ·		
	roundwaterDistance from	nearest fresh water well	Distance from nearest surface
water			
Pit Liner Thickness:	mil Below-Grade Tank: \	Volumet	obls; Construction Material
<ol><li>Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</li></ol>			
	INTENTION TO:	1	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON	☐ REMEDIAL WORL	CONTREPORT OF:  Control  Cont
TEMPORARILY ABANDON	CHANGE PLANS	☐ COMMENCE DRII	
PULL OR ALTER CASING	☐ MULTIPLE COMPL	☐ CASING/CEMENT	JOB 🔲
OTHER:		OTHER:	DETUDN TO DOOD JOST OF
13. Describe proposed or	completed operations. (Clea	rly state all pertinent de	RETURN TO PRODUCTION  ails, and give pertinent dates, including
Commated date of Start	ring any proposed work). SEI completion or recompletion.	ERULE 1103. For Multi	ple Completions: Attach wellbore
<b>1/22/09-2/2/09</b> MIRU	well service Install ROD To:	et cooing to EDO# for 20	min w/ no leak off. RIH w/ bit,
drill collars and 2 7/8 to	ubing. Tag cement at 4915'	Drill out cmt and CIRD a	min w/ no leak off. RIH w/ bit, t 4931'. RIH and tag at 5083'.
Drill out to 5114'. Drill	out iron sulfide to 5130'. Drill	out suspected 2nd bride	14931. Kin and tag at 5083'.
Drill out to 5114'. Drill out iron sulfide to 5130'. Drill out suspected 2nd bridge plug at 5130'. Push down to 5450'. Circulate out paraffin and iron sulfide from 5450' to 5715'. Begin drilling cement at 5717'. Stop			
drilling at 57 19°. Riff open end to 5706'. Spot 2000 gal 15% NEFE HCL at 5706' across perfe at 409.4'.			
3919. Full tubing up to 4383'. Pump 95 BBI 2% KCL at 4 BPM at 600# to displace acid from casing			
Load to recover 150 BBL. Rig up swab. Swab back 50 BBL. POH w/tubing RIH w/ Centrilift P-8, 800			
BPD ESP, 239 stages, 77 HP motor at 47.80' long pump, 2 7/8" seating nipple and 180 joints 2 7/8" tubing. Pump intake at 5578'. Btm of pump motor at 5600'. Nipple up wellhead. Test ESP. RDMO			
nulling unit Turn well	55/8'. Btm of pump motor a	it 5600'. Nipple up wellh	nead. Test ESP. RDMO
pulling unit. Turn well over to production dept			
hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached)			
SIGNATURE I	// >		
SIGNATURE / Lut / / Type or print name KENT V	VILLIAMS E-mail addr		DATE <u>2/4/09</u>
For State Use Only	VILLIAMS E-mail addı	ess:	Геlephone No. (432)689-5200
APPROVED		ROLEUM ENGINEER	
BY: Conditions of Approval (if any):	TITLE_FEI	INSTRUM CIACINGEQ	DATE_FEB 1 1 2009
- Andrews of Abbioagi (II appar.			