

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

|                                                    |                                                                        |
|----------------------------------------------------|------------------------------------------------------------------------|
| WELL API NO.                                       | 30-025-06705                                                           |
| 5. Indicate Type of Lease                          | STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil / Gas Lease No.                       |                                                                        |
| 7. Lease Name or Unit Agreement Name               | C. L. HARDY                                                            |
| 8. Well No.                                        | 4                                                                      |
| 9. Pool Name or Wildcat                            | PENROSE SKELLY GRAYBURG                                                |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3494'                                                                  |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
CHEVRON USA INC

3. Address of Operator  
15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location  
Unit Letter M : 660' Feet From The SOUTH Line and 660' Feet From The WEST Line  
Section 20 Township 21-S Range 37-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3494'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ PLUGBACK TO GRAYBURG

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-07-03: MIRU KEY UNIT #176.  
10-08-03: REL TAC. TIH TO 5166'.  
10-09-03: TIH W/RBP & SET @ 5100. SPOT 3 SX SAND ON TOP OF RBP. (NEW PBD @ 5086'). PUH TO 4510. TIH W/GR/CBL/CCL LOGGING TOOL. PULL CBL LOG FR 5080-2600 W/400 PSI.  
10-10-03: PERF 3667-73, 3683-86, 3690-93, 3696-3700, 3709-13, 3716-20, 3724-30, 3744-48, 3760-64, 3780-83, 3792-98, 3806-10, 3816-20, 3834-40, 3848-52, 3861-67. 71' & 284 HOLES. TIH W/PPI PKR.  
10-13-03: ACIDIZE GRAYBURG PERFS 3667-3867 W/3200 GALS 15% ANTI-SLUDGE HCL. SET PPI PKR @ 3646. RU SWAB 3 HR TEST.  
10-14-03: RU SWAB. 9 HR TEST.  
10-15-03: REL PKR @ 3605. SET FRAC PKR @ 3508.  
10-16-03: FRAC GRAYBURG PERFS 3667-3867 W/66,000 GALS YF135 & SAND.  
10-17-03: RU SWAB. 7 HR TEST. RUN TEMP SURVEY FR 3300-4200. RUN AFTER FRAC PRISM LOG FR 4000-3500.  
10-20-03: REL FRAC PKR @ 3508.  
10-21-03: SN @ 3637. EOT @ 3673. SET TAC @ 3385. RIG DOWN. TURN WELL OVER TO PRODUCTION TO SET PUMPING UNIT & RUN RODS.  
11-03-03: ON 24 HR OPT. PUMPING 6 OIL, 225 GAS, & 226 WATER.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 11/4/2003  
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED Paul G. Hargis TITLE PETROLEUM ENGINEER  
CONDITIONS OF APPROVAL, IF ANY:

DATE

DEC 09 2003

2A Blinberry 046