

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other Water Injection

2. Name of Operator
EOG Resources Inc.

3a. Address
P.O. Box 2267 Midland, Texas 79702

3b. Phone No (include area code)
432 686 3689

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FNL & 2310' FEL U/L J /
Sec 18, T18S, R33E

5. Lease Serial No

NM 93 104050

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No.

Corbin Federal 4
Delaware Unit

9. API Well No

30-025-25448

10. Field and Pool, or Exploratory Area

Corbin Delaware; West

11. County or Parish, State

Lea NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Prep for P&A

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Prep well for P&A

1. POOH w/ 2-7/8" tubing and packer.
2. Set a 5-1/2" CIBP at 5000' (Delaware perfs 5032 - 5062').
3. Run a CBL log to determine TOC behind 5-1/2" casing.
4. A P&A sundry will be submitted after evaluation of the CBL.

5-1/2" casing was originally cemented with a 2 stage cement job with a DV tool at 1433'.

Cement was not circulated off of the DV tool after the 1st stage so the TOC below the DV tool is unknown. Cement was circulated to the surface on the 2nd stage from 1433'.

RECEIVED

APR 08 2010

HOBBSDO

APPROVED

/s/ Roger Hall
APR - 2 2010

Field Engineer
BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Stan Wagner

Title Regulatory Analyst

Date 3/26/10

Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

DISTRICT SUPERVISOR/GENERAL MANAGER
Office

Date

APR 09 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction