Office	e of New Mexico	Form C-103 June 19, 2008
District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88216 District III 1000 Rio Brazos Rd, Aztec, NM 87410 0 3 2010 District IV Energy, Minerals and Natural Resources CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-05506
		5. Indicate Type of Lease
		STATE x FEE
1220 S. St. Francis Dr., Santa 中的BBSOCD 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		SUNRISE STATE 25
1. Type of Well: Oil Well X Gas Well Other		8. Well Number #2
2. Name of Operator CHI OPERATING,INC.		9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
212 N. MAIN, MIDLAND, TEXAS 79701		BOWERS, SEVEN RIVERS
4. Well Location Unit Letter Program to NOPTH Single and 1000 Single Season to FAST 1		
Unit LetterB:_330feet from theNORTH line and1980_feet from theEAST_line Section 25 Township 18S Range 37E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
GL-3662'; KB-3680'		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON		
PULL OR ALTER CASING		
_		_
OTHER: 13. Describe proposed or completed operations. (C		rkover give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
2/12/10 Dig out Dry Hole Marker, MIRU unit, pipe racks & tally tbg, clean pins & boxes. NU BOP & RU reverse unit. PU swivel, make		
up bit, NU stripper, drill cmt plug f/18-222', circ hole clean, drill cmt 222-283', hole clean, RD swivel, RU tbg tools, PU tbg, tag plug @		
1502', drill cmt 1502-1593', circ hole clean, tag cmt @ 2408, drill cmt 2408-2477', circ hole clean, clean reverse pit & fill tank w/fresh		
Wtr, drill cmt 2477-2622', circ hole clean, tag cmt @ 2729', drill cmt 2729-2820', wash t/2911, circ hole clean, PU tbg total 111jts + BHA = 3623'. Tst csg t/250psi-ok. Circ hole w/2% KCL wtr. RU WL & run CNL & RBL f/3600-surface. Perf well 4spf 3283-		
3288,3319-3327'. Acidize w/4000gal 7½% NeFe HCL. Frac well w/20,450 16/30 SLC. 3/9/10 ND BOP & NU WH. W/O pumping unit.		
4/21/10 PU new pump, PU the rods, space well out to tag on btm, hang well on.		
Spud Date: Work over 2/12/10	Pig Palagga Data: Workover 3/	/9/10
Spuu Date.	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE KOLM (SILL)		
SIGNATURE 1000000000000000000000000000000000000		
Type or print nameROBIN ASKEW For State Use Only	E-mail address:	PHONE:432-685-5001
PETROLEIMA PAIGANGED		
APPROVED BY: DATE DATE DATE		