

RECEIVED

Submit One Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

APR 04 2011

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
January 20, 2011

HOBBSUCD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-005-00909
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Rock Queen Unit
8. Well Number	99
9. OGRID Number	247128
10. Pool name or Wildcat	Caprock; Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other Injector

2. Name of Operator Celero Energy II, LP

3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701

4. Well Location
Unit Letter B : 660 feet from the N line and 1650 feet from the E line
Section 34 Township 13S Range 31E NMPM _____ County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	P AND A <input type="checkbox"/>
MULTIPLE COMPL <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	<input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A

All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
 A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the **OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
 - Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
 - If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
 - All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
 - All other environmental concerns have been addressed as per OCD rules.
 - Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
 - If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service company equipment, has been removed from lease and well location.
- When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Lisa Hunt TITLE Regulatory Analyst DATE 03/31/2011
 TYPE OR PRINT NAME Lisa Hunt E-MAIL: lhunt@celeroenergy.com PHONE: (432)686-1883
 For State Use Only

APPROVED BY: Mary Brown TITLE Compliance Officer DATE 4/7/2011
 Conditions of Approval (if any):