



New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

John H. Bemis
Cabinet Secretary-Designate

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division



April 13, 2011

Apache Corporation
6120 S. Yale, Suite 1500
Tulsa, OK 74136

Apache Corporation
303 Veterans Airpark Lane
Suite 3000
Midland, TX 79705

DENIAL OF REQUEST FOR ALLOWABLE AND AUTHORIZATION TO TRANSPORT

Re: Apache Corporation, OGRID #873

- W H Laughlin #11, API #30-025-39909, Lea County, New Mexico

Dear Operator:

The Oil Conservation Division (OCD) **denies** your request for allowable and authorization to transport for the wells identified above because your company is out of compliance with 19.15.5.9(A) NMAC [Part 5.9(A)]. See 19.15.16.19(A)(4) NMAC.

Your company is out of compliance with Part 5.9(A) on the following ground(s):

XXXX Financial assurances. Your company is in violation of the financial assurance requirements for well plugging set out in 19.15.8.9 NMAC. See 19.15.5.9(A)(1) NMAC. Specifically, your company has not posted the single-well financial assurances required for state or fee wells which have been inactive for more than two years. The wells requiring single-well financial assurances are identified in the attached sheet.

_____ **Corrective action.** Order _____, issued on _____ after notice and hearing, found your company to be in violation of an order requiring corrective action. See 19.15.5.9(A)(2) NMAC.

_____ **Unpaid penalties.** Your company has not paid the penalties assessed against your company in _____, issued on _____. More




than 70 days have passed since the issuance of the order assessing the penalty. See 19.15.5.9(A)(3) NMAC.

_____ **Inactive wells.** According to the attached inactive well list, your company has too many wells in violation of the inactive well rule (19.15.25.8 NMAC) that are not subject to an inactive well agreed compliance order. See 19.15.5.9(A)(4) NMAC. As an operator of _____ wells, your company may have no more than _____ wells in violation of the inactive well rule. Your company has _____ wells in violation of the inactive well rule. In addition,

I have enclosed an information sheet explaining the requirements of Part 5.9. You may re-submit your request after your company has returned to compliance with Part 5.9.

Respectfully yours,



Daniel Sanchez
OCD Compliance and Enforcement Manager

Ec: Jami Bailey, OCD Director, Santa Fe
Theresa Duran-Saenz, OCD Legal Assistant, Santa Fe
Larry "Buddy" Hill, OCD District 1 Supervisor
Randy Dade, OCD District 2 Supervisor
Charlie Perrin, OCD District 3 Supervisor
Ed Martin, OCD District 4 Supervisor
Sonny Swazo, OCD Assistant General Counsel

Inactive Well Additional Financial Assurance Report

873 APACHE CORP

Total Well Count: 2548

Printed On: Wednesday, April 13 2011

Well Name	Le as e Ty pe	ULSTR	OC D Uni t Let ter	API	W ell Ty pe	Last Prod/ Inj	Inactive Additio nal Bond Due	Meas ured Dept h	Req uire d Bon d Amo unt	Bon d Req uire d Now	Bo nd In Pl ac e	In Viola tion
J R PHILLIPS GAS COM #001	P	1-1 - 20S- 36E	A	30-025- 04130	G	03/2 009	04/01 /2011	390 0	890 0	Y	0	Y
NORTHEAST DRINKARD UNIT #622	P	C-15- 21S- 37E	C	30-025- 34649	O	03/2 009	04/01 /2011	684 0	118 40	Y	0	Y

INFORMATION SHEET FOR PART 5.9

Oil Conservation Division (OCD) Rule 19.15.5.9 NMAC, commonly known as “Part 5.9,” requires operators to meet certain minimum compliance standards for the wells they already operate before they can drill, acquire, produce or inject into additional wells. If an operator is out of compliance as defined by Part 5.9, the OCD:

- May deny registration by the operator or certain related entities. *See* 19.15.9.8(B) NMAC.
- May deny applications for change of operator that would transfer wells to the operator. *See* 19.15.9.9(C) NMAC.
- Must deny injection permits. *See* 19.15.26.8(A) NMAC.
- May deny APDs. *See* 19.15.14.10(A) NMAC.
- Must deny allowable and authorizations to transport. *See* 19.15.16.19(A) NMAC.

In addition, the OCD may, after notice and hearing, revoke previously issued injection permits if the operator is out of compliance with Part 5.9. *See* 19.15.26.8(A) NMAC.

To stay in compliance with Part 5.9, an operator must:

- Keep current with the financial assurance requirements for well plugging. *See* 19.15.5.9(A)(1) NMAC.
- Comply with orders requiring corrective action. *See* 19.15.5.9(A)(2) NMAC.
- Pay properly assessed penalties. *See* 19.15.5.9(A)(3) NMAC.
- Have no more than a certain number of wells out of compliance with the inactive well rule. *See* 19.15.5.9(A)(4) NMAC.

FINANCIAL ASSURANCE REQUIREMENTS: The OCD’s financial assurance requirements for well plugging are set out in 19.15.8.9 NMAC. The OCD requires all state or fee wells to be covered by a financial assurance. The OCD does not require financial assurances for Federal or Indian wells.

The operator must either post a blanket financial assurance in the amount of \$50,000 to cover its state or fee wells, or post single-well financial assurances for each state or fee well in the amount set by the rule.

If the operator chooses to post a blanket financial assurance, it must also post single-well financial assurances for each state or fee well that has been inactive for more than two years that has not been plugged and released. Note that a single-well financial assurance is required even if the well is on approved temporary abandonment status, and even if the wellbore of the well has been plugged. To check compliance with this requirement, go to www.emnrd.state.nm.us/OCD, OCD Online, E-Permitting, Compliance, Financial Assurance. Insert the operator name or OGRID, and hit “Get Report.” The report will list all the wells for that operator that have not been plugged and released. Wells currently in violation of the single-well financial assurance requirement will have a “Y” in the far right column, titled “In Violation.”

For information on how to post financial assurances, please contact OCD Financial Assurance Administrator Dorothy Phillips, (505) 476-3461, Dorothy.phillips@state.nm.us.

CORRECTIVE ACTION REQUIREMENTS: If an operator fails to take an action required by a hearing order or an agreed compliance order, the OCD may go to hearing to obtain a formal order finding the operator “in violation of an order requiring corrective action.” Once such an order is issued and becomes final, the operator will be out of compliance with Part 5.9 until that order is lifted. To lift the order, the operator must

complete the corrective action required, and file a motion to declare the order satisfied. The Oil Conservation Division or the Oil Conservation Commission, as appropriate, may grant the motion without hearing or may set the matter for hearing.

UNPAID PENALTIES: An operator with a penalty assessment unpaid more than 70 days after issuance of the order assessing the penalty will be in violation of Part 5.9 until that penalty is paid. Penalties may be assessed by the district court, or may be agreed to by the operator under an agreed compliance order entered into to resolve a compliance action.

INACTIVE WELLS: The inactive well rule, 19.15.25.8 NMAC, requires any well that has been inactive for a period of more than 15 months to be plugged and abandoned, placed on approved temporary abandonment status, or returned to production or other beneficial use. An operator will be out of compliance with Part 5.9 if it has too many wells in violation of the inactive well rule; the number of non-compliant wells allowed depends on the size of the operator. Under Part 5.9, if an operator operates:

- 1 well, it may have no wells out of compliance;
- 2 or 3 wells, it may have no more than 1 well out of compliance;
- 4 to 100 wells, it may have no more than 2 wells out of compliance;
- 101 to 500 wells, it may have no more than 5 wells out of compliance;
- 501 to 1000 wells, it may have no more than 7 wells out of compliance; and
- 1000 or more wells, it may have no more than 10 wells out of compliance.

To check compliance with 5.9 as to inactive wells, go to www.emnrd.state.nm.us/OCD, OCD Online, E-Permitting, Compliance, Inactive Well List. Do not change the default search terms. Insert the operator name or OGRID, and hit "Get Report." The report will identify the wells that -- according to OCD records -- have been inactive for 15 months, are not on approved temporary abandonment status, do not have a plugged wellbore, and are not subject to an inactive well agreed compliance order. For purposes of Part 5.9, if a well appears on this list, there is a rebuttable presumption that the well is in violation of the inactive well rule. The heading of the list will also identify the total well count for the operator, and the total number of non-compliant inactive wells, so you can determine if the operator is in compliance with Part 5.9.

If your company has more non-compliant wells than allowed under Part 5.9, you will need to return wells to compliance by returning them to production or other beneficial use, placing them on approved temporary abandonment status, or plugging the wellbore. In some limited circumstances, the OCD may be willing to enter into an inactive well agreed compliance order setting a schedule for returning the wells to compliance and imposing sanctions if that schedule is not met. Wells covered by an inactive well agreed compliance order are not included when calculating Part 5.9 compliance. For information on inactive well agreed compliance orders, contact OCD Attorney Sonny Swazo at (505) 476-3463, Sonny.swazo@state.nm.us.