

COPIES RECEIVED		
CONTRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator <u>Gene Milford dba Milford Pipe &amp; Supply</u>	9. Well No. <u>1</u>
4. Location of Well <u>Box 427 Tatum, NM 88267</u>	10. Field and Pool, or Wildcat <u>Chaveroo San Andres</u>
UNIT LETTER <u>M</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>7-S</u> RANGE <u>33-E</u> NMPM.	12. County <u>Roosevelt</u>
15. Elevation (Show whether DF, RT, GR, etc.)	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:      SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged & abandoned as follows:

3-18-74  
Set CIBP @ 3990  
Dumped 35' cement plug from 3990' to 3955'  
Shot 4 1/2" Csg @ 1503' & 1393'  
Recovered csg. 1393'  
Spotted 40 sk cmt plug from 393 to 1253'  
Spotted 50 sk cmt plug from 500' to 380'  
Spotted 10 sk smt plug from 10' to surface  
Installed dry hole marker

Note: All plugs set witha and hole circulated w/ brine salt gelled mud.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gene Milford TITLE owner DATE 4-17-74

APPROVED BY John W. Runyan TITLE Geologist DATE FEB 22 1974

CONDITIONS OF APPROVAL, IF ANY: