

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6659	
7. Unit Agreement Name -	
8. Farm or Lease Name Hobbs "Y"	
9. Well No. 1	
10. Field and Pool, or Wildcat undesignated	
15. Elevation (Show whether DF, RT, GR, etc.) 4188 GL	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	
2. Name of Operator Charles B. Read	
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201	
4. Location of Well UNIT LETTER J, 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 12S RANGE 34E NMPM.	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	

7-19-70: Report of Plug and Abandonment

Set 35 sx plug cmt 10,036' to 9,736'

Cut and removed 5 1/2" @ 7310'

Cut and removed 8 5/8" @ 550'

Ran tubing to 7,316' and filled hole with mud

Set plugs as follows:

25 sx plug	7316' to 7247'
11 11 11	5611' to 5540'
11 11 11	4216' to 4146'
11 11 11	589' to 533'
11 11 11	434' to 390'
10 sx plug	10' to 0'

Installed regulation Marker. Will notify when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles B. Read TITLE Agent DATE 7-21-70

APPROVED BY John W. Runyan TITLE Geologist DATE FEB 18 1972

CONDITIONS OF APPROVAL, IF ANY: