

Submit: 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised March 25, 1999

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-025-35985
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> <b>P</b>
6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 Oil Well  Gas Well  Other  O/G

2. Name of Operator  
~~Concho Oil & Gas, Corp.~~ **Riches Exploration Inc**

3. Address of Operator  
 110 W. Louisiana, Ste 410 Midland, TX 79701

4. Well Location  
 Unit Letter N : 330' feet from the North line and 2000' feet from the East line  
 Section 27 Township 12S Range 38E NMPM County Lea

7. Lease Name or Unit Agreement Name:  
 Burrus

8. Well No.  
 #5

9. Pool name or Wildcat  
 Trinity Wolfcamp

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
 3797' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Spud & Set Intermed. Casing <input checked="" type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  
 9/19/02- MIRU Big Dog rig #13. Spud 17 1/2" hole to 400'. Ran 13 3/8" 48# H40 8rd casing & set @ 400'. Cmt csg w/441 sxs "C" + additives. Circ 103 sxs to surface. WOC (18 hrs).  
 9/21/02- NU BOP & test to 1000 psi. Tag cmt @ 335' & test to 1000 psi-ok. Resume drlg.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Bustamante TITLE Production Analyst DATE 9/24/02

Type or print name Dora Bustamante Telephone No. (915) 683-7443

(This space for State use)

APPROVED BY GARY W. WINK ORIGINAL SIGNED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 14 2002