

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-2745800
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-992-9

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name State LF-30
2. Name of Operator Matador Operating	8. Well No. 2
3. Address of Operator 415 W. Wall, Ste. 1101 Midland, TX 79701	9. Pool name or Wildcat So. Kemnitz Atoka/Morrow
4. Well Location Unit Letter <u>H</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>1480</u> Feet From The <u>West</u> Line Section <u>30</u> Township <u>16S</u> Range <u>34E</u> NMPM <u>Lea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Remove permanent pkrs. at 13,018' and 13,214'. Squeeze Atoka perms @ 12750-764, Morrow perms 13068-80 and Morrow perms 13160-173.

Run production equipment. Place Morrow perms 13250-266 back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Russ Mathis TITLE Production Manager DATE 7/17/97
 TYPE OR PRINT NAME Russ Mathis (915) 687-5955 TELEPHONE NO.

(This space for State Use)

APPROVED BY Charles Kerr TITLE _____ DATE 8-1-97
 CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTION