

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
LG 883

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER- P&A
Name of Operator
Yates Petroleum Corporation
Address of Operator
207 South 4th St., Artesia, NM 88210
Location of Well
UNIT LETTER M 990 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 16S RANGE 32E NMPM.

7. Unit Agreement Name
8. Form of Lease Name
Bunker Hill WB State
9. Well No.
1
10. Field and Pool, or Whichever Und.
Bunker Hill Grayburg
12. County
Lea

11. Elevation (Show whether DF, RT, GR, etc.)
4250' KB; 4242' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
--	---	---	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-31-82 - Pulled 63 joints of 4-1/2" casing for total of 2055'.
Plugged well as follows:
Plug #1: Spot 50 sx plug at 3621-2989'. Tagged plug at 2989'.
Plug #2: Spot 50 sx plug at 2626'. Tagged plug at 2467'.
Plug #3: Spot 35 sx plug at 1157'. Tagged plug at 1017'.
Plug #4: Spot 10 sx plug at surface.

Install dry hole marker. Location will be restored.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APPROVED BY Ronald M. Little TITLE Production Supervisor DATE 6-22-83
APPROVED BY Ronald M. Little TITLE OIL & GAS INSPECTOR DATE JAN 16 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 07 1983
O.C.D.
HOBBS OFFICE