

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.  
LEASE DESIGNATION AND SERIAL NO.

LC-077826-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR <b>Tenneco Oil Company</b>	7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR <b>7 Hobbs Pipe &amp; Supply Co. Box 2010, Hobbs, N.M.</b>	8. FARM OR LEASE NAME <b>Featherstone</b>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  <b>2310' FWL and 1032' FWL of Sec. 31</b>	9. WELL NO. <b>1</b>
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT <b>Watkins - 7 Rivers</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>31-182-R 32 E</b>
	12. COUNTY OR PARISH <b>Lea</b>
	13. STATE <b>N.M.</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT? <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spot a 25 sx plug at shoe of 7" casing.
2. Load hole with mud ladin fluid.
3. 1500' - 7" casing recovered.
4. A 25 sx plug at stub of 7".
5. A 20 sx plug from 1100' to 1200'.
6. A 25 sx plug was spotted at 10 3/4" casing shoe.
7. A 40 sx plug at 10 3/4" casing stub at 395'.
8. A 25 sx plug at 300'.
9. A 25 sx plug in top with regulation marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

*D. Decker*

TITLE

*Agent*

DATE

**4-12-67**

(This space for Federal or State office use)

APPROVED BY

TITLE

**APPROVED**

DATE

CONDITIONS OF APPROVAL, IF ANY:

OCT 4 1968

\*See Instructions on Reverse Side

J L GORDON  
ACTING DISTRICT ENGINEER

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.