

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TPIH
(Other Instructions
reverse side)

ATD
8-16

Form approved
Budget Bureau No. 12-R1121

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Continental Oil Company	8. FARM OR LEASE NAME NIX "C"
3. ADDRESS OF OPERATOR P. O. Box 450, Hobbs, New Mexico 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' TSL & 660' FWL, Section 13, T-18 S, R-35 E, Lea County, New Mexico	10. FIELD AND POOL, OR WILDCAT BOKES-DEVONIAN
14. PERMIT NO.	15. ELEVATIONS (Show whether DT, RT, CG, etc.) 3883 DF
	12. COUNTY OR PARISH Lea
	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The well was abandoned by the following procedure:
1. Pulled tubing and packer @ Spotted 50 sh. cent. plug from
perfs: 12075-12163. ② Set 5" csg. @ 7261 ④ Spotted
50 sh. cent. plug from 6000' to 5900' ⑤ Spotted 50 sh.
cent. plug from 3850-3750 ⑥ Left 8" casing in hole
⑦ Set 50 sh. cent. plug @ 600' ⑧ Set 50 sh. cent. plug
@ 350' ⑨ Set 10 sh. cent. plug @ ground level
⑩ Installed dry hole marker and cleaned up.
Location. PVA-1-17-69

18. I hereby certify that the foregoing is true and correct

SIGNED M. E. Yeakley

TITLE Administrative Section Chief

DATE 1-20-69

(This space for Federal or State only use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

USGS(5) Shuffelarger, FILE