

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 26
8. Well No. 411
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3679' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER INJECTOR

2. Name of Operator
SHELL WESTERN E&P INC.

3. Address of Operator
P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location
Unit Letter A : 330 Feet From The NORTH Line and 330 Feet From The EAST Line
Section 26 Township 18S Range 37E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Frac trtd</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-16 to 11-24-89:
POH w/inj equip. CO to 4247' (tagged btm). Ran base GR/temp log from 4226' to 4100'. CO to 4248'. Acid Grayburg perfs 4163' - 4241' w/1000 gals 15% NEFE HCl. Frac trtd perfs 4163' - 4241' w/2125 gals YF130 frac fl + 10,500# Brady sd. Tagged sd @ 4195'. Circ'd out sd to 4248' (FBTD). Ran afterfrac GR/Temp survey. Inst inj equip, setting Guib Uni-VI PKr @ 4107'. Pres tstd csg to 500# for 30 min, held OK. Ret'd to inj.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 1-08-90

TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)
APPROVED BY _____ TITLE _____ DATE JAN 12 1990

CONDITIONS OF APPROVAL, IF ANY: